

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS
 CLAIM

1164977
 WEB

CLAIM ORIGIN
 ORIGINAL CLAIM ID
 VIN 5ZT2FESB9NW025663
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 320 / 320
 ITEM # FET274RKS-320
 DEALER RO # 68086
 CLAIM START DATE 07/29/2022
 CLAIM END DATE 01/01/1900

Labor rate: \$150.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code
 30-99-01-00-001016

Operational Description

Mini-Blind Hold Down Bracket - Interior/Soft Goods/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-29 15:58:11 :: BLIND MOUNTS ODNT LINE UP WITH BLINDS removed mounts and realigned the blinds. filled holes with putty

Model #

Dlr Sub Hrs

0.05

Sub Labor Amt \$7.50

Serial #

Appr Hrs

0.05

Appr Labor Amt \$7.50

Notes

Labor

Line# 2

Operation Code
 30-91-01-00-000901

Operational Description

Rocker, Recliner, or Glider Chair - Interior/Living Quarters, Sofa, Chair/ Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-29 15:59:51 :: ONE RECLINER DOESNT WORK removed bolts holding recliners to get behind them to find the problem. after moving the recliners found that the plug was not plugged in. plugged in power source, now chairs work as should on all functions

Model #

Dlr Sub Hrs

0.20

Sub Labor Amt \$30.00

Serial #

Appr Hrs

0.20

Appr Labor Amt \$30.00

Notes

reposition recliner and plug in

Labor

Line# 3

Operation Code
 10-11-01-00-000205

Operational Description

Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/ No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-29 16:01:21 :: SLIDE ROOM SEAL IS LOOSE seal is a peal and stick it fell down. put seal back in place, shot a screw in place to hold seal

Model #

Dlr Sub Hrs

0.60

Sub Labor Amt \$90.00

Serial #

Appr Hrs

0.30

Appr Labor Amt \$45.00

Notes

re-secure slide room seal

Labor

Line# 4

Operation Code
 30-104-01-00-001201

Operational Description

Dinette Cushion Cover - Interior/Cushions-Dinette-Mattress-Curtains/ Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-29 16:02:42 :: DINNET SCREW COVER IS MISSING made a new set then clipped on to the dinnete set

Model #**Serial #****Dlr Sub Hrs**
Appr Hrs**0.20**
0.05**Sub Labor Amt** ~~\$30.00~~
Appr Labor Amt \$7.50**Notes**

install fabric covered snap button 70-150-02-00-001753

Labor
Line# 5**Operation Code**

30-101-24-00-001078

Operational Description

Sliding, Pocket Door - Interior/Interior Doors/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-29 16:03:31 :: BEDROOM DOOR HAS NO STOPPER put a screw in place to stop the door from falling off the track

Model #**Serial #****Dlr Sub Hrs****Appr Hrs****0.20****0.05****Sub Labor Amt** \$30.00**Appr Labor Amt** \$7.50**Notes**

install 1 stop screw = 0.05

Labor
Line# 6**Operation Code**

10-9-15-00-000168

Operational Description

Polymax Underbelly - Frame & Chassis/Levelers, Underbelly/Repair or Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-29 16:04:50 :: UNDER BELLY HAS TAPE DRAGGIN GTO THE GROUND underbelly tape came off the underbelly and stuck to the axle. retaped the underbelly and removed the tape.

Model #**Serial #****Dlr Sub Hrs****Appr Hrs****0.20****0.20****Sub Labor Amt** \$30.00**Appr Labor Amt** \$30.00**Notes**

re-secure underbelly tape

Submitted

Labor Amt	\$217.50
Parts & Freight	\$0.00
Total	\$217.50

Approved

Labor Amt	\$127.50
Parts & Freight	\$0.00
Total	\$127.50

DEALER**DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER**DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.