



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68086

CUSTOMER WORK ORDER

WO #: 68086

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0803 CHECK PREAUTH

Stock #: 11122
Stock Desc: 2022 TT COACHMEN
FREEDOM EXPRESS 274RKS
Chassis #: 5ZT2FESB9NW025663
Serial #: 5ZT2FESB9NW025663
Mileage:
Licence:

Invoice #:
Date In: 27 JUL 22
Promised:
Date Sched:
Completed: 31 JUL 22
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: BLIND MOUNTS ODNT LINE UP WITH BLINDS

CORRECTION: removed mounts and realigned the blinds. filled holes with putty

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	7.50

Subtotal for Job #1: 7.50

Job #2 - Warranty

COMPLAINT: ONE RECLINER DOESNT WORK

CORRECTION: removed bolts holding recliners to get behind them to find the problem. after moving the recliners found that the plug was not plugged in. plugged in power source, now chairs work as should on all functions

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	30.00

Subtotal for Job #2: 30.00

Job #3 - Warranty

COMPLAINT: SLIDE ROOM SEAL IS LOSOE



Customer #: 1000
BASDEN'S AMERICAN RV,



CORRECTION: seal is a peal and stick it fell down. put seal back in place, shot a screw in place to hold seal

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	45.00
Subtotal for Job #3:			45.00

Job #4 - Warranty

COMPLAINT: DINNET SCREW COVER IS MISSING

CORRECTION: made a new set then clipped on to the dinnete set

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	7.50
Subtotal for Job #4:			7.50

Job #5 - Warranty

COMPLAINT: BEDROOM DOOR HAS NO STOPPER

CORRECTION: put a screw in place to stop the door from falling off the track

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	7.50
Subtotal for Job #5:			7.50

Job #6 - Warranty

COMPLAINT: UNDER BELLY HAS TAPE DRAGGIN GTO THE GROUND

CORRECTION: underbelly tape came off the underbelly and stuck to the axle. retaped the underbelly and removed the tape.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	6.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	24.00
Subtotal for Job #6:			30.00

Parts Total:	0.00
Labour Total:	127.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	127.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Aug 2022



Customer #: 1000
BASDEN'S AMERICAN RV,

