

Approved date 8/16/2022

8/27/2021

KRV – In lieu of part return, please provide a photo of the valve showing the defect & any markings; photos must show valve uninstalled & open. This will expedite review & approval for the claim.

Correction: TRIED TO MOVE BOTH CABLES AND THEY WERE STUCK, CUT 2 HOLES IN UNDER BELLY TO FIND TO END OF CABLES, REMOVED BOTH SET SCREWS AND PULLED OUT OF VALVES, TOOK BOTH NUTS OFF AT T HANDLE AND REMOVED BOTH CABLES AND THEY NEED REPLACED, FILLED OUT SHEET TO ORDER, PARTS ORDERED, got parts in and pulled camper in bay and put both cables back in place and tested, both work fine, sealed up underbelly with extreme tape.

Complaint: ON THE KITCHEN SLIDE OUT CLOSER TO THE
BED ROOM IS LOOSE TRIM
Cause: TRIM LOOSE
Correction: on the dinette side nailed in fascia and filled in
holes for nails.

2-Authorization number PA03222361

4.60

paper claims only use one pre-authorization number per warranty claim for

[illegible]