

e-Authoization

8/16/20
03:34:54

3-Authorization number PA03216142 Reference no: 68171 Status: Approved Approved by papca Approved date 8/11/2022
Tracing Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTGGR20NV506310 5/20/2022
600 E Baseline Rd
Evansville, IN 47725

Item	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2312014A Windshield - Fron	0.00	2.00	1.00		1	0.50	Complaint:FRONT CAP WINDOW IS LEAKING IN BETWEEN THE TRIM PIECES, MIGHT BE COMING FROM THE LIGHT MARKED WITH BLUE TAPE Cause:FOUND WINDOW LEAKING Correction:CHECKED ROOF AND I TOUCHED UP SOME SPOTS,,CHECKED ARC ON FRONT AND TOUCHED UP ONE AREA,CHECKED FRONT WINDOW AND PULLED BACK RUBBER TRIM AND IT HAD GAPS IN OTHER RUBBER AROUND WINDOW,SEALED THE TOP OF WINDOW AND PUT RUBBER TRIM BACK ON LET DRY AND WATER TEST IT,STILL LEAKED SEALED AROUND WINDOW RING,LET DRY AND TESTED WITH WATER AND CHECKED INSIDE,NO SIGNS OF LEAKS. KRV - REPAIR ONLY approved.
2	2300118F Entrance Door - t	0.00	0.30	0.20		1	0.20	Complaint:THE ENTRY DOOR AND THE SCREEN DOOR ARE HARD TO OPEN,,,, THE HANDLE ON THE SCREEN DOOR WILL NOT MOVE VERY EASY Cause:LUBED LATCH Correction:TOOK SCREEN DOOR LATCH OFF AND LUBED AND THE LATCH FREED UP INSTALLED LATCH BACK IN PLACE.DOSENT STICK ANYMORE. KRV - REPAIR ONLY approved.
3-Authorization number PA03216142				1.20				

paper claims only use one pre-authorization number per warranty claim for
Please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the