



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68180
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 68180

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0913 FIND OUT FROM JP IF
THIS CAN BE COSED

Stock #: 10963

Stock Desc: 2023 5W KEYSTONE

COUGAR HALF-TON 27SGS

Chassis #: 4YDFCGM25PV500817

Serial #: 4YDFCGM25PV500817

Mileage: 0

Licence:

Invoice #:

Date In: 04 AUG 22

Promised: 31 AUG 22

Date Sched:

Completed: 14 SEP 22

Warr. Date:

Job #1 - Warranty

COMPLAINT: CHECK STOVE NOT INSTALLED RIGHT

CAUSE: Stove top is bent and the front of the stove above where the knobs are located is bent. The stove has also got into the countertop a little bit. Rear post that holds stove top is bent. Rear vent for oven is also bent.

CORRECTION: REMOVED THE STOVE TOP AND STRAIGHTENED THE VENTS. ALIGNED THE STOVE TO COUNTER TOP. THEN PUT NEW STOVE TOP ON. CHECKED THE ORIGINAL OVEN DOOR THERE IS NO DAMAGE, SO I DIDNT REPLACE IT. THE KNOB FACE PLATE IS BROKEN TOOK PICTURE. GOT WITH DENNY ABOUT STOVE

bring unit in, open up, get parts from parts room, remove range from cabinet, disconetng gas and 12vdc lines, remove screws holding back on, discont gas lines from oven valve, disconet thermal cuppler from valve, pull back away from oven to get hand down inside of wall to remover thermostast line from oven, put new valve body under old valve body on top of range and start transferring wires from one valve body to the other valve body, 3 of the spark wires the ends broke off befor comming loose from the sparker, find ends and put new ends on wires, run 12vdc test wires to range and test lights and spark, install range in cabinet conet gas line, conet 12vdc lines, turn on gas and test, check for gas leak with gas detition fluid on all contions that was changed, all butners light and all lights liteclean up and put old parts in partsroom, close unit up and pull out

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	0.00
Z990	MISCELLANEOUS REPAIR	SAR	54.00
Z990	MISCELLANEOUS REPAIR	SAR	96.00
Z990	MISCELLANEOUS REPAIR	JP	0.00

Parts

Part #	Description	Qty	Price	Total
677570	Range - Top Tray Module Only - 21" - 2 in 1 Range Oven - Black - F1S21L02A-BL - C-F1S17L02A-002	1.00	176.13	176.13
686833	Range - Oven Door Assembly - 21" Door - w/Black Trim and Silver Handle - For F1S21L02A-BL - (C-F1S21L02A-BL-021)	1.00	156.62	156.62
677573	Range - Front Panel Module - Black - w/Stainless Steel, Silver Knobs, Ignitor Included - For F1S21L02A-BL - (C-F1S170L02A-BL-005)	1.00	299.37	299.37

Customer #: 1000
BASDEN'S AMERICAN RV,



Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT FOR ALL PARTS	1.00	115.41	115.41
Subtotal for Job #1:				897.53

Parts Total: 632.12
Labour Total: 150.00
Sublet Total: 0.00
Extras Total: 115.41
WORK ORDER TOTAL: 897.53

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 Sep 2022

W/O: 68180
Promised Date: 31 AUG 22



Customer #: 1000
BASDENS AMERICAN RV,

