

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68199
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 21435 - JAMES R. EDWARDS
Address: 3775 W 200 S JASPER, IN

47546

Phone: 812-309-0641

Stock Number: 11242 - 2023 COUGAR HALF-TON 30BHS 4YDTCGP25PL500486

VIN: 4YDTCGP25PL500486 HIN:

SER#: 4YDTCGP25PL500486

Mileage: 0

Work Order Comp: 17 FEB 23

Auth. No:

Dealer #: 1194

Warr. Date: 18 AUG 22

Work Order Date: 06 AUG 22

Inv #: 387602

WO # Job # Description JOB INFORMATION

68199 1 FRONT METAL DENTED.
WAITING ON APPROVAL 8/11/22
Went and got metal out of trailer. Removed metal from box.
Removed insert trim from Top piece and halfway up both sides.
removed all mounting screws for transition strip and side pieces.
Removed mounting screws from bottom. Cut around silicone and
decals. Removed top insert trim. Pulled Corner trim away from
front metal piece so I could pull it out from underneath the
fiberglass above it. Removed metal from camper. Got new piece of
metal and positioned on the front. Centered metal piece and
secured the screws to the bottom of the frame. Tucked the top
piece under the fiberglass. Applied butyl tape to the top
transition strip and the side pieces as needed. Secured all
mounting screws on transition strip on both sides. Secured top
transition strip. Top transition strip was not hitting anything
in the middle so I had to slightly lower the transition strip.
Cleaned up silicone on the top transition strip. Cleaned area
with mineral spirits. Taped all areas off with blue tape. Applied
silicone around all edges and seems. Installed insert trim along
the top piece and both sides. Cleaned up mess.

68199 8 7WAY JUNCTION BOX NOT SECURED TO FRAME
junction box is secured to frame.7 way/ battery shut off junction
box is broken. need to replace.

68199 2 STAIN ON CHAIR

Claim : 68199

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
          STAIN ON CHAIR "BOTTOM CUSHION"
          REMOVED WITH MINERAL SPIRITS.

68199      3      PLASTIC DOOR FRAME IS LOOSE BATHROOM
          SECURE TO STUD WITH SCREW.
          FOUND A SCREW THAT MATCHED THE OTHER ONES AND SECURED FRAME TO
          WOODEN STUD BEHIND IT.

68199      4      TABLE HAS SCRATCHES VERY LIGHT
          SCRATCHES ON TABLE TOP.
          CLEANED WITH MINERAL SPIRITS. APPLIED WAX TO A RAG AND REMOVED
          SCRATCHES.

68199      5      SEAM TAPE BY DOOR CAME LOOSE
          SEAM TAPE IS LOOSE AT THE BOTTOM NEAR FLOOR.
          APLLIED SUPER GLUE TO SEAM TAPE AND SET BLOCK IN FRONT OF IT TO
          HOLD AGAINST WALL.

68199      6      BEDROOM ENTRY DOOR EEDS ADJ
          BOTTOM OF DOOR IS HITTING THE FRAME BEFORE THE REST OF THE DOOR.
          TOOK A SMALL BLOCK OF WOOD AND TAPED IT TO THE BOTTOM OF THE DOOR
          FLANGE. SHUT THE DOOR AND PUSHED THE BOTTOM OF THE DOOR INWARD.

68199      7      MAIN ENTRY DOOR NEEDS ADJUSTED
          ENTRY DOOR ISNT LATCHING.
          MOVED DOOR LATCH CLOSER TO OUTSIDE OF FRAME.

```

```

*****
Part No    Job#   Description      PARTS      Qty      Price      Total
*****
634544      1      SKIRT - METAL - 030 - 34" x 96" - 1.00      86.31      86.31
APP017-412406 1      CLEAR SIKASIL PLUS 1.00      17.86      17.86
682807      8      Box - 12v Power Distribution - TT 1.00      131.36      131.36

```

```

*****
Lab Code   Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      1      MISCELLANEOUS REPAIR 0.00      150.00      0.00
Z990      1      MISCELLANEOUS REPAIR 0.00      150.00      0.00
Z990      1      MISCELLANEOUS REPAIR 0.00      150.00      0.00
Z990      1      MISCELLANEOUS REPAIR 0.00      150.00      0.00
Z990      1      MISCELLANEOUS REPAIR 3.00      150.00      450.00
Z990      8      MISCELLANEOUS REPAIR 0.50      150.00      75.00
Z990      8      MISCELLANEOUS REPAIR 0.00      150.00      0.00
Z990      2      MISCELLANEOUS REPAIR 0.30      150.00      45.00
Z990      3      MISCELLANEOUS REPAIR 0.20      150.00      30.00
Z990      4      MISCELLANEOUS REPAIR 0.20      150.00      30.00

```

Claim : 68199

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      5    MISCELLANEOUS REPAIR      0.10     150.00     15.00
Z990      6    MISCELLANEOUS REPAIR      0.20     150.00     30.00
Z990      7    MISCELLANEOUS REPAIR      0.20     150.00     30.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT       1    FREIGHT & CRATE - METAL      1.00     140.46     140.46
FRT       8    UPS-BREAKER BOX             1.00      18.70      18.70

```

```

Parts Total:      235.53
Labour Total:     705.00
Sublet Total:       0.00
Extras Total:     159.16

```

>>>> Claim Total: 1,099.69

Customer Signature: _____

Date: _____