

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS

Authorized

WEB

CLAIM ORIGIN

ORIGINAL CLAIM ID

VIN

5ZT2CAMB6PU041011

CHASSIS VIN

MILEAGE

0

SITE/WAREHOUSE

103 / 103

ITEM #

CAT231MKS-8

DEALER RO #

68212

CLAIM START DATE

08/11/2022

CLAIM END DATE

01/01/1900

Labor rate: \$150.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 50-134-01-00-001454 LP Bottle Cover - LP Gas/LP Gas System/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-08-11 13:56:21 :: MISSING LP TANK COVER NEED TO REPLACE
 Model # **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$30.00
 Serial # **Appr Hrs** 0.00 **Appr Labor Amt** \$0.00

Notes

THE COVER IS NOT OFFERD ON 2023 MODELS
 THE COVER IS NOT OFFERD ON 2023 MODELS

Labor

Line# 2 **Operation Code** **Operational Description**
 20-46-02-00-000721 Window - Exterior/Windows/Adjust/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-08-11 13:57:21 :: GLUE ON SLIDE OUT WINDOW CLUE ON SLIDE OUT WINDOW FROM FACTORY. NEEDS REMOVED USED ADHISSIVE REMOVER TO TAKE GLUE OFF.
 Model # **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$45.00
 Serial # **Appr Hrs** 0.20 **Appr Labor Amt** \$30.00

Notes

EXCESSIVE TIME REQUESTED ADJUSTED TO FLAT RATE

Labor

Line# 3 **Operation Code** **Operational Description**
 70-469-01-00-004028 Refrigerator Shelf - Glass or Wire - Appliances/Refrigerator (Furrion)/
 Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-08-11 13:58:18 :: FRIDGE BRACKET HAS TAPE ON IT AND VERY DIRTY THERE WAS TAPE ON FRIDGE BRACKET ON NEW UNIT REMOVED TEP AND TAPE ADHISSIVE
 Model # NA **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$30.00
 Serial # NA **Appr Hrs** 0.10 **Appr Labor Amt** \$15.00

Notes

EXCESSIVE TIME REQUESTED ADJUSTED TO FLAT RATE

Labor

Line# 4 **Operation Code** **Operational Description**
 30-99-01-00-001014 Mini-Blind or Vertical Patio Blind Wand - Interior/Soft Goods/Replace/No
 Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-08-11 13:59:21 :: MISSING MINI BLIND WAND
WOND MISSING

Model #
Serial #

Dlr Sub Hrs
Appr Hrs

0.05
0.00

Sub Labor Amt
Appr Labor Amt

\$7.50
\$7.50

Notes

AUTHORIZED AS REQUESTED

Labor
Line# 5

Operation Code

30-102-12-00-001096

Operational Description

Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior
Moldings/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-08-11 14:00:00 :: GLUE ON SLIDE ROOM TRIM
GLUE ON SLIDE ROOM TRIM. FROM FACTORY NEEDS CLEANED OFF CLEANED OFF GLUE ON SLIDEROOM
TRIM

Model #
Serial #

Dlr Sub Hrs
Appr Hrs

0.15
0.15

Sub Labor Amt
Appr Labor Amt

\$22.50
\$22.50

Notes

AUTHORIZED AS REQUESTED

Submitted

Labor Amt	\$135.00
Parts & Freight	\$0.00
Total	\$135.00

Approved

Labor Amt	\$75.00
Parts & Freight	\$0.00
Total	\$75.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.