

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68215
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 51775 - PAUL A. SHIVELY
Address: 105 MEADOW HILL RD CAMPBELLSVILLE, KY

42718
Phone: 270-789-8017
Stock Number: 11039 - 2022 SABRE 38DBQ 5ZT3SR3B0N6108551
VIN: 5ZT3SR3B0N6108551 HIN: SER#: 5ZT3SR3B0N6108551
Mileage: 0 Work Order Comp: 31 OCT 22
Auth. No: Dealer #:
Warr. Date: 23 AUG 21 Work Order Date: 09 AUG 22 Inv #: 384969

WO # Job # Description JOB INFORMATION

68215 6 THE DRIP GUARD OVER THE MAIN DOOR WAS SET TOO LOW. CUSTOMER
ADJUSTED IT, BUT HE WOULD LIKE US TO VERIFY THAT IT IS CORRECT.
REMOVED FACTORY DRIP RAIL OVER ENTRY DOOR AND REPLACED WITH NEW
FROM WARRANTY. TRIMED WITH SILICONE

68215 8 THERE IS A GAP WHERE THE BACK WALL MEETS THE OFF DOOR SIDE.
FOUND NO DAMAGE TO THE WALL COMING APART. READJUSTED THE J WRAP
AT THE CORNER AS IF IT WAS NOT SET BEHIND CORNER TRIM. REMOVED
THE SCREWS AND RAN LONGER SCREWS IN TO PULL CORNER TOGETHER.
RETRIMED WITH SILICONE. 11-4-22, REMOVED DAMAGED DECAL ON OFF
DOOR SIDE AT THE BACK WALL. CLEANED AND LAYED NEW DECAL IN PLACE.
REMOVED CORNER CAP AND SCREWED IN NEW CORNER CAP, TRIMED WITH
SILICONE.

68215 9 WHEN CUSTOMER IS ON CITY WATER, THE FRESH TANK FILLS WITH WATER.
HAD TO GO INSIDE OF THE BASEMENT AND REMOVE THE ACCESS PANEL TO
REMOVE THE WATER PUMP. BENCH TEST THE FLOW BACKWARDS. THE CHECK
VALVE LEAKS. HAVE PICTURES OF WATER PUMP SITTING IN WATER FROM
LEAK. GOT NEW WATER THEN INSTALLED IN SAME LOCATION AS BAD PUMP.
CHECKED FOR LEAKS.

68215 2V243 RECALL 22V243 LP QUICK CONNECT
removed recall lp quick connect, then installed new quick connect
that was provided

68215 3 THE KITCHEN SLIDE REAR RUBBER SEAL HAS BEEN FOLDED OVER AND

Claim : 68215

 WO # Job # Description JOB INFORMATION

SEALED. IT NEEDS TO BE SLIDE UPWARDS AND SECURED.
 REMOVED SCREW AND MOVED SEAL UP , THEN PUT A SCREW AT TOP ALONG
 WITH BOTTOM SILICONED TO TRIM OUT SEAL

68215 4 THE BAR THAT ROLLS WHEN THE KITCHEN SLIDE GOES IN IS SECURED WITH
 WIRE INSTEAD OF A BOLT. THIS IS LOCATED IN THE SAME AREA AS LINE
 1.
 REMOVED THE WIRE IT WAS THERE FROM FACTORY

 Part No Job# Description PARTS Qty Price Total

F100145307	6	SLIDE OUT, 192" WHITE RIGID CO-EX		1.00	15.50	15.50
F100073147	8	DECAL, 2019-22 SABRE COBALT DC 16		1.00	5.26	5.26
F100182488	8	LOWER REAR CORNER CAP -LARGE		1.00	3.50	3.50
F100114311	9	REVOLUTION ON DEMAND PUMP		1.00	110.99	110.99

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.20	150.00	30.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.50	150.00	75.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.50	150.00	75.00
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	V243	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.20	150.00	30.00

 Excode Job# Description EXTRAS Qty Price Total

FRT	6	FREIGHT-DRIP RAIL		1.00	200.00	200.00
FRT	8	UPS-DECAL AND CORNER CAP		1.00	15.93	15.93

Parts Total: 135.25
 Labour Total: 300.00
 Sublet Total: 0.00
 Extras Total: 215.93

>>>> Claim Total: 651.18

Customer Signature: _____

Date: _____