

8/17/20
02:10:44 PM

Approved date 8/10/2022

Retail sold on

Basden's American RV
600 E Baseline Rd
Evansville, IN 47725

Root operation of

1	1202206B	Power Jack, Moto	0.00	0.50	0.50	1	0.50	Complaint:COVER ON FRONT STAY JACK MOTOR IS
---	----------	------------------	------	------	------	---	------	---

Complaint:COVER ON FRONT STAY JACK MOTOR IS MISSING
Cause:COVER IS MISSING
Correction:NEED TO INSTALL NEW COVER //// IM SORRY SOMETHING THAT IS ON THE DAF FORM NEED TO BE FIXED. IF YOU HAVE A PROBLEM PLEASE CALL ME 8128675200 EXT263
KRV – Labor time approved in accordance with Keystone RV's flat rate manual.
VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only)

0.50

Each paper claims only use one pre-authorization number per warranty claim for

Attach a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the