

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68253
MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11244 - 2023 INTREPID 210 59CCC2328PL006536

VIN: 59CCC2328PL006536 HIN: SER#: 59CCC2328PL006536

Mileage: 0 Work Order Comp: 12 SEP 22

Auth. No: Dealer #:

Warr. Date: Work Order Date: 12 AUG 22 Inv #: 382528

WO # Job # Description JOB INFORMATION *****

68253 7 BLACK TANK FLUSH HOSE PINCHED FLAT
BLACK TANK FLUSH HOSE PINCHED FLAT.
Cut pinched section of black tank flush hose out. Installed 90
deg elbow with clamps. Checked for leaks. OK.

68253 1 SHOWER SURROUND PULLING AWAY. NOTED ON DEL
SHOWER SURROUND PULLING AWAY. NOTED ON DELIVERY.
Shower surround bowed between fasteners. Added more fasteners in
bowed areas. Sealed edge of shower surround with white silicone.

68253 2 4 BLINDS IN SLIDE WILL NOT STAY UP
4 BLINDS IN SLIDE WILL NOT STAY UP.
Tightened strings on all window blinds on slideout.

68253 3 STAPLE HOLES NEED FILLED IN CABINET UNDER SINK
STAPLE HOLES NEED FILLED IN CABINET UNDER SINK.
Filled staple holes with matching putty.

68253 4 STAPLE HOLES IN MEDICINE CABINET
STAPLE HOLES IN MEDICINE CABINET.
Filled all holes in medicine cabinet.

68253 6 DEAD BOLT WILL NOT LOCK
DEAD BOLT WILL NOT LOCK.
Door frame material will not dead bolt plunger lock. Cleared out
material for plunger to extend and lock.

Claim : 68253

 WO # Job # Description JOB INFORMATION

68253 8 GREY TANK NOT READING CORRECT ON MONITOR
 GREY TANK NOT READING CORRECT ON MONITOR PANEL.
 It takes a long time for monitor to show 1/3 and then it jumps to full. Changed wires on grey tank. Moved full wire to extra sensor at top of tank. Grey tank now reads full. Open dupm valve and monitor gradually drops from full to 2/3 to 1/3 to empty. Started filling grey tank again. Monitor will read 1/3 for a long time, Then go to 2\3 and then full. Monitor panel now reading ok. Drains are slow.

 Part No Job# Description PARTS Qty Price Total

 10-0901 7 BARB ELBOW 1/2 X 1/2 1.00 0.86 0.86

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.40 150.00 60.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.37 150.00 55.50
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.13 150.00 19.50
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.20 150.00 30.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 1.00 150.00 150.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00

Parts Total: 0.86
 Labour Total: 405.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 405.86

Customer Signature: _____

Date: _____