

e-Authorization

8/30/20
05:36:25

Authorization number PA03225218 Reference no: 68266 Status: Approved Approved by angjr Approved date 8/30/2022
 Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDT26021M3105465 1/23/2021
 600 E Baseline Rd
 Evansville, IN 47725

Job #	Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2102706A	Wall - Metal Sidin	0.00	10.00	8.00		1	0.50	Complaint: CUSTOMER HAS NOTICED THAT THE METAL ON OFF SIDE IS PULLING LOOSE BETWEEN THE FRONT OF THE CAMPER AND THE FIRST WINDOW RIGHT ABOVE IT Cause: THE STAPLES ARE NOT HOLDING THE METAL AND IT IS BOWING OUT Correction: NEED TO PULL METAL OFF AND FIX SO IT IS NOT BOWING ANYMORE -----removed all windows and blinds, exhaust vent, front radius corner trim, rear corner trim, pulled staples out of metal and removed one section at a time all the way up to affected area. set metal to the side. got a lift and secured the top piece of metal to the studs. took next piece of metal and connected it to the top piece. secured with staples. repeated these steps until all metal was secured. took a piece of wood and turned it sideways to help push bottom piece out while we pushed the last 'bottom piece into the track. secured front and rear pieces of metal with staples. cleaned windows and installed new butol tape. installed windows and blinds, exhaust vent, front and rear corner trim with butol tape. cleaned up edges and applied silicone to front and rear radius trim. siliconed top caps of windows. HELPED ZAC FINISH CAMPER KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

Authorization number PA03225218
 8.00

For paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the