



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68290
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 68290

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0831 CHECK PREAUTH

Stock #: 10966

Stock Desc: 2023 TT KEYSTONE
KEYSTONE 25RDS

Chassis #: 4YDTCGM26PL500534

Serial #: 4YDTCGM26PL500534

Mileage: 0

Licence:

Invoice #:

Date In: 16 AUG 22

Promised: 31 AUG 22

Date Sched:

Completed: 30 AUG 22

Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: LP TANK WILL NOT FILL

CAUSE: LP TANK WILL NOT FILL UP AT ALL. NEED NEW TANK

CORRECTION: GOT NEW LKP TANK AND FILLED UP

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00

Parts

Part #	Description	Qty	Price	Total
66-4907	L.P.CYLINDER 30 LB. PW	1.00	89.70	89.70

Other Services

Code	Description	Qty	Price	Total
LP30	30LB. LP CYLINDER FILL	1.00	20.00	20.00

Subtotal for Job #1: 139.70

Customer #: 1000
BASDEN'S AMERICAN RV,





Job #2 - Warranty

COMPLAINT: BEDROOM SIDE TABLE HAS STAPLE HOLES ON IT

CAUSE: BEDROOM SIDE TABLE HAD A ROW OF UNFILLED STAPLE HOLES IN IN

CORRECTION: FILLED IN STAPLE HOLES WITH WOOD PUTTY

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	0.00
Z990	MISCELLANEOUS REPAIR	RAB	150.00

Subtotal for Job #2: 150.00

Job #3 - Warranty

COMPLAINT: STOVE LIGHT NOT HOOKED UP RIGHT

CAUSE: STOVE LIGHT WAS NOPT WIRED UP. NEEDS REWIRED

CORRECTION: STRIPPED WIRE AND CRIMPED ONJ CONNCTOR AND TESTED

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00

Subtotal for Job #3: 30.00

Job #4 - Warranty

COMPLAINT: BATHROOM DOOR TRIM NEEDS ADJ

CAUSE: BATHROOM DOOR TRIM NEEDS ADJUSTED IT WAS HITTING THE SIDE TRIM NEEDED TO BE CUT

CORRECTION: CUT AND AJUSTED TRIM AND REINSTALLED

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	15.00

Subtotal for Job #4: 15.00

Parts Total: 89.70
 Labour Total: 225.00
 Sublet Total: 0.00
 Extras Total: 20.00
WORK ORDER TOTAL: 334.70

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Aug 2022

