

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

Labor rate: \$150.00
 OWNER INFORMATION

CLAIM STATUS
 CLAIM
 CLAIM ORIGIN
 ORIGINAL CLAIM ID
 VIN 5ZT2FEHB5NW022119
 CHASSIS VIN 0
 MILEAGE 320 / 320
 SITE/WAREHOUSE FET192RBS-320
 ITEM # 68336
 DEALER RO # 08/27/2022
 CLAIM START DATE 01/01/1900
 CLAIM END DATE

Authorized
 1209271
 WEB

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor
 Line# 1 Operation Code 70-147-24-00-001761 Operational Description
 Winegard TV Antenna On Off Power Supply Booster - Appliances/
 Television/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-08-27 14:39:26 :: TV ANTENNA NOT PICKING UP CHANNELS I REMOVED THE BOOSTER AND RADIO. I CHECKED ALL OF THE CABLE ENDS. I TRYED A NEW BOOSTER. I REMOVED THE ANTENNA AND FOUND THAT THE CABLE END WAS NOT INSTALLED RIGHT. I CUT OFF THE OLD CABLE END AND INSTALLED A NEW ONE. I TESTED THE TV AGAIN AND IT WAS NEW WORKING. I REINSTALLED THE ANTENNA ON THE ROOF AND PUT THE BOOSTER BACK INTO THE WALL. TESTED THE TV AGAIN AFTER EVERYTHING WAS PUT TOGETHER. SYSTEM IS WORKING AS IT SHOULD.

Model #	Dlr Sub Hrs	1.00	Sub Labor Amt	\$150.00
Serial #	Appr Hrs	1.00	Appr Labor Amt	\$150.00

Notes

Labor
 Line# 2 Operation Code RC-026-01-00-004186 Operational Description
 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY
 (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread
 Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-08-27 14:40:28 :: RECALL 22V243 LP QUICK CONNECT INSTALLED NEW LP QUICK DISCONNECT AND TESTED

Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00
Serial #	Appr Hrs	0.60	Appr Labor Amt	\$90.00

Notes

Did you inspect/replace BOTH quick disconnects? All Freedom Ultra Lites and Freedom Liberty/Maple Leaf Models will require 2 quick disconnects. One for the frame mounted quick disconnect location on the unit and one for the gas supply line attached to the griddle. Recall is not complete until BOTH are inspected/replaced.
 DIDNT KNOW THERE WAS TWO BOTH HAS BEEN INSPECTED AND REPLACED

Submitted	Labor Amt	\$195.00	Approved	Labor Amt	\$240.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$195.00		Total	\$240.00

DEALER

DATE

CUSTOMER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

SIGNATURE

All repairs described have been inspected and are satisfactory.