

Pre-Authorization

8/29/20
01:38:42 PM

Pre-Authorization number PA03233804 Reference no: 68366
Submitting Name Address

Status: Approved
VIN

Approved by papca
Retail sold on

Approved date 8/29/2022

34 Basden's American RV Basden's American RV
600 E Baseline Rd
Evansville, IN 47725 4YDTGGM27PL500512

Job Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
--------------------------	-------------	--------	-----------	-------------------	-----------------	-----	---------------	--------------------------------

1	2312014A Windshield - Fron	0.00	1.00	0.50		1	0.50	Complaint:WATER LEAKING IN FRONT CAP WINDOW Cause:WATER LEAKING IN FRONT CAP WINDOW. Correction:Rubber seal around window in front cap has a small gap allowing water to get in and drip on mattress in front bedroom. Pulled rubber seal off across top and around both top corners. Sealed gap across top of window with clear silicone. Replaced rubber seal. Taped Next to rubber seal at top and around both top corners. Added clear silicone and removed tape from top of window and top corners. KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
---	----------------------------	------	------	------	--	---	------	--

Pre-Authorization number PA03233804

0.50

This paper claims only use one pre-authorization number per warranty claim for
multiple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the