

aim Response

8/30/2022
05:28:47 pm

Non-Warranty Goodwill Adjustment

Last Modified by: ambri

Item	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
198233	68371	8/26/2022	8/26/2022	4YDT26029M3106816	1194	Basden's American RV	600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	2/27/20

Qty	Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved

Component Model: 6020 Component Serial Number: N 20 36

Operation	Description	Srvc advisory	Sub hours	Apv'd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444 NOTE: THIS UNIT IS LOCATION # 80 Cause: LP REGULATOR RECALL Correction: INSTALLED NEW LP REGULATOR AND TESTED (AP/KRV)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & sublet 56.11
Submitted labor & sublet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 131.11

Approved parts & sublet 56.11
Approved labor & sublet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 131.11