

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68380
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 51925 - PACKY G. KERMICLE
Address: 615 S MILL ST OLNEY, IL

62450

Phone: 618-839-2053

Stock Number: 10645 - 2022 CATALINA 263BHCKLE 5ZT2CARB1NU039463

VIN: 5ZT2CARB1NU039463 HIN:

SER#: 5XT2CARB1NU039463

Mileage: 0

Work Order Comp: 27 SEP 22

Auth. No:

Dealer #:

Warr. Date: 09 OCT 21

Work Order Date: 24 AUG 22

Inv #: 383135

WO # Job # Description JOB INFORMATION

68380 2 FIX WOOD DAMAGE
REMOVE FRIDGE. REMOVE CABINET DOORS. REMOVE SHELF INSIDE OF
CABINET. REMOVE FRONT CABINET FACE.. CUT AND DRILL POCKET HOLES.
BUILD NEW FRONT CABINET FACE. INSTALL NEW ON CABINET AND PUT BACK
FRIDGE. REMOVE CONVERTOR .REMOVE LOWER CABINET FACE AND INSTALL
NEW ONE.

68380 1 CUSTOMER KEEPS UNIT PLUGGED TO SHORE AND KEEPS REFRIGERATOR ON
WHEN PARKED AT THEIR PROPERTY AND AT THEIR CAMP. CUSTOMER
RETURNED TO THE CAMPER TO FIND THAT THERE WAS APPROX 4-6 INCHES
OF ICE INSIDE THE REFRGERATOR. THE ICE BEGAN TO MELT THEN RAN
OUT OF THE REFRIGERATOR AND CAUSED WATER DAMAGE TO THE WOODEN
TRIM BELOW THE REFRIGERATOR. SEE BW FOR ADDITIONAL DETAILS.
FRIDGE AREA IS BUILDING UP WITH ICE. NOTICED THE DOOR IS HITTING
AT THE BOTTOM. LET FRIDGE THAW OUT AND NEED TO ADD A SHGIM ON THE
BOTTOM BRACKET TO SEE IF THAT HELPS SEAL THE DOOR
ADDED PLASTIC SHIM TO BOTTOM BRACKET. LEAVING UNIT PLUGGED IN FOR
TESTING. 9/2/22

68380 2V243 RECALL 22V243 LP QUICK CONNECT
lp quick connect is part of the recall. needs replaced
removed quick connect. installed new quick connect per
instructions

68380 BRAKE JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL
FOUND WIRING INCORRCET

Claim : 68380

 WO # Job # Description JOB INFORMATION

 FIXED WIRING

 Part No Job# Description PARTS Qty Price Total

 F100130701 2 RI-MOLD #150 1-7/8" X 8' VIPER TR 1.00 3.65 3.65
 F100285215 2 .75X.75 STILE 24.00 0.47 11.28
 F100285189 2 STILE, LC 18MM" X 5-1/4" X 8' SQU 24.00 2.56 61.44
 F100285188 2 3" CABINET STILE 24.00 1.38 33.12
 F100285187 2 2.5" STILE 24.00 1.23 29.52
 F100285185 2 STILE, LC 18MM" X 2" X 8' SQUARE 24.00 0.95 22.80
 C01226204 2 RETURN AIR GRILL 1.00 17.25 17.25

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 3.00 150.00 450.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 3.00 150.00 450.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 150.00 30.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 V243 MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00
 Z990 RAKE MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 RAKE MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 2 FREIGHT/CRATE 1.00 167.10 167.10

Parts Total: 179.06
 Labour Total: 1,020.00
 Sublet Total: 0.00
 Extras Total: 167.10

>>>> Claim Total: 1,366.16

Customer Signature: _____

Date: _____