

aim Response

8/30/2022
04:14:04 pm

aim: C3197463

Non-Warranty Goodwill Adjustment

Last Modified by: mbri

Item Reference no.

Repair start date

Repair date VIN

Pre-auth

Dealer Repairing dealer name

Labor rate

Changed Type warranty rate

Date of Purchase

197463 68401

8/25/2022 8/25/2022 4YDT26729LK414465

1194 Basden's American RV
600 E Baseline Rd
Evansville, IN 47725

150.00

0.00 SA21-414 5/23/20

Item Name

Quantity Qty Returned Dealer price Markup

Part total

Appr Freight Sub Freight

Sublet

Status

696405 Regulator - Recall Only Kit - A 1.00 0.00 25.00 15.00 28.75 0.00 0.00 0.00

18749. Dealer claiming 48.79/56.11

Component Model: 6020 Component Serial Number: N 19 29

Operation Description

Svc advisory Sub hours Apv'd Hours

Labor amt

Sublet

Qty Base Hours

Status

7141442B Safety Advisory 21-414 Winn-Tec

0.50

0.50

75.00

0.00

1

0.50

Approved

Complaint: KEYSTONE SAFETY ADVISORY LP
REGULATOR RECALL #21-414
SECTION:71 COMPONENT:414
OPERATION:7141442B
PART#380444
Cause: LP REGULATOR RECALL
Correction: INSTALLED LP REGULATOR AND
TESTED
(Deking/KRV)

5218749

Submitted parts & sublet 28.75
Submitted labor & sublet 75.00
Submitted freight: 0.00
Tax: 0.00

Total Submitted: 103.75

Approved parts & sublet 28.75
Approved labor & sublet 75.00
Approved freight 0.00
Tax: 0.00

Total approved: 103.75