

aim: C3211421 Non-Warranty Goodwill Adjustment Last Modified by:ambri

aim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type	Date Of Purchase
211421	68437	9/12/2022	9/12/2022	4YDT27423K3100622	1194	Basden's American RV	600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414 4/15/20

Item #	Item Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
7141442K	Safety Advisory 21-414 Winn-Tec	1.00	0.00	0.00	15.00	0.00	0.00	0.00	0.00	Approved

Component Serial Number: N 17 29

Complaint: KEYSTONE SAFETY ADVISORY LP  
REGULATOR RECALL #21-414  
SECTION:71 COMPONENT:414  
OPERATION:7141442B  
PART#380444  
Cause: LP REGULATOR RECALL. DOES NOT MEET THE ONE THAT NEEDS TO BE CHANGED  
Correction: NO ACTION REQUIRED

KRV- covering INSP only as original regulator not part of recall population

Submitted labor & sublet	Submitted freight	Tax	Total Submitted:	Approved labor & sublet	Approved freight	Tax	Total approved:
45.00	0.00	0.00	45.00	45.00	0.00	0.00	45.00