

e-Authorization

9/2/20
06:03:39 p

3-Authorization number PA03240269 Reference no: 68442 Status: Approved Approved by stumli Approved date 9/2/2022
rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDF32321M4704827 8/27/2021
600 E Baseline Rd
Evansville, IN 47725

lu Root e operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201606B Batten Tape - Ref	0.00	0.20	0.20		1	0.20	Complaint:TAPE UP STAIRS ON RIGHT SIDE HAS TAPE COMING OFF BUY FLOOR Cause:FOUND TRIM FALLING OFF Correction:pulled off trim and pulled out staples and redid tape on wall and installed trim back in place.
2	3201606B Batten Tape - Ref	0.00	0.20	0.20		1	0.20	Complaint:TAPE BEHIND COACH COMING OFF Cause:TAPE COMING OFF Correction:did not find anything behind couch but found it on side of couch,smoothed tape back in place.
3	3102714A Dinette Table - Re	0.00	0.40	0.20		1	0.20	Complaint:LATCH FOR TABLE NOT LOCKING IN IN BACK AND HAS CAME LOOSE AND CABINET NEEDS TOUCHED UP. Cause:INSTALL ISSUE Correction:checked table lock and made hole bigger, for latch to fit in,works great now. KRV - VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only) KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
4	3201116A Door - Interior Slic	0.00	0.20	0.20		1	0.30	Complaint:LEFT FRONT MIRROR TRACK NOT HOLD UP MIRROR Cause:INSTALL ISSUE Correction:INSTALLED EXTRA SCREWS TO CATCH WOOD IN CEILING.
5	3200206B Door - Interior Hin	0.00	0.40	0.10		1	0.10	Complaint:TOP HINGE ON BATHROOM DOOR MOSSING SPACER, (HANGING OUT) Cause:INSTALL HINDGE Correction:FOUND A HINGE AND REPLACED IT. KRV - VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only) KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
6	4201816A Awning - Main - H	0.00	0.10	0.10		1	0.50	Complaint:WIRING COVER INSIDE AWNING ARMKEEPS

r paper claims only use one pre-authorization number per warranty claim for
iple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
n. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

Pre-Authorization

9/2/20
06:03:39 PM

Job Root Operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
7 6104025A	Shower/Tub - Wal	0.00	0.10	0.10		1	0.50	FALLING OUT. IS INSIDE ON COUNTERTOP Cause: IT FELL OUT Correction: took picture and snapped back in place. KRV - VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only)
								Complaint: ONE OF THE RUBBER GASKETS ON THE SHOWER DOOR IS NOT FITTING CORRECTLY. Cause: seal came off Correction: pushed seal back and taped to place in place on top and bottom. KRV - VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only)
3-Authorization number PA03240269				1.10				

paper claims only use one pre-authorization number per warranty claim for
 a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the