



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68465
Promised Date: 30 SEP 22

CUSTOMER WORK ORDER

WO #: 68465

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 1020 CHECK WORK

Stock #: 11251

Stock Desc: 2023 TT COACHMEN

CATALINA 243RBSLE

Chassis #: 5ZT2CANB8PU041140

Serial #: 5ZT2CANB8PU041140

Mileage: 0

Licence:

Invoice #:

Date In: 02 SEP 22

Promised: 30 SEP 22

Date Sched:

Completed: 20 OCT 22

Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*68717 on 01 OCT 22

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: WHEN UNIT WAS DELIVERED THE STOVE FELL
OUT AND IS ON THE FLOOR

CAUSE: DOOR THAT WAS SENT IS WRONG. THE DOOR WE NEED IS STAINLESS.

CORRECTION: PULLED UNIT INTO SHOP. REMOVED DAMAGED DOOR. INSTALLED NEW DOOR.
HOOKED UP WIRES AND GAS LINE. SECURED STOVE TO COUNTER. CLEANED GLASS OUT OF
INSIDE. CLEANED UP MESS.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
7483	RV17D-OVEN DOOR FOR CF-17 DIGITAL	1.00	72.34	72.34

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-OVEN DOOR	1.00	16.63	16.63

Subtotal for Job #1: 238.97



Customer #: 1000
BASDEN'S AMERICAN RV,



Job #2 - Warranty

THE WOODEN STILES ARE DAMAGED UNDER THE STOVE.

Labor		Mechanic		Total
Code	Description			
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS		300.00

Parts		Qty	Price	Total
Part #	Description			
F100285185	STILE, LC 18MM" X 2" X 8' SQUARE	8.00	0.95	7.60
	CHILI TEAK 47001759 MC 2022			
F100285188	3" CABINET STILE	8.00	1.38	11.04

Other Services		Qty	Price	Total
Code	Description			
FRT	UPS - STILES	1.00	154.34	154.34

Subtotal for Job #2:				472.98
-----------------------------	--	--	--	---------------

Job #3 - Warranty

COMPLAINT: THE TRIM ON THE SLIDE OUT ROOM IS LOOSE

CAUSE: TRIM WAS LOOSE ON SLIDE OUT CEILING

CORRECTION: SECURED TRIM WITH BRAD NAILS

Labor		Mechanic		Total
Code	Description			
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS		15.00

Subtotal for Job #3:				15.00
-----------------------------	--	--	--	--------------

Job #4 - Warranty

COMPLAINT: THE ENTRY DOOR HITS THE DOOR FRAME WHEN OPENING AND CLOSING

CAUSE: entry door hits the latch when trying to open and shut.

CORRECTION: took hammer and a block of wood and moved latch away from door.

Labor		Mechanic		Total
Code	Description			
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS		15.00

Subtotal for Job #4:				15.00
-----------------------------	--	--	--	--------------

Job #5 - Warranty

COMPLAINT: THE WINDOW GLAZING IS COMING OUT OF THE SLIDE OUT WINDOW.

CAUSE: WINDOW GLAZING ON BOTTOM CORNER OF SLIDE OUT WINDOW CAME LOOSE

CORRECTION: PUSHED GLAZING BACK ONTO WINDOW FRAME

Labor		Mechanic		Total
Code	Description			
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS		30.00

Subtotal for Job #5:				30.00
-----------------------------	--	--	--	--------------

Job #6 - Warranty

COMPLAINT: THERE ARE STAINS ON THE COUCH.

CAUSE: STAINS ON COUCH

CORRECTION: REMOVED STAINS WITH MINERAL SPIRITS AND A RAG





Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	15.00
Subtotal for Job #6:			15.00

Job #7 - Warranty

COMPLAINT: THE SHOWER SURROUND NEEDS TO BE SEALED

CAUSE: SHOWER SURROUND IS LEAKING IN CORNERS WHEN TESTING SHOWER.

CORRECTION: SEALED INSIDE CORNERS WITH SILICONE.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	45.00
Subtotal for Job #7:			45.00

Job #8 - Warranty

THE STAPLES ABOVE THE SLIDE OUT ARE EXPOSED.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	150.00

Parts	Description	Qty	Price	Total
Part #				
500627	CLEAR SIKASIL PLUS	2.00	17.86	35.72
PUTTY	PUTTY TAPE - ROLL	1.00	7.12	7.12
20-6963	Insert Molding Trim Type; 1-1/4 Inch Height x 1/3 Inch Width x 16 Foot Length; Black; Aluminum	1.00	37.94	37.94
5460	BLACK PUTTY TAPE 1" x 20'	1.00	6.27	6.27
5981	Trim - Screw Cover - 76 - Narrow Vinyl - Black	1.00	1.62	1.62
Subtotal for Job #8:				238.67

Job #9 - Warranty

COMPLAINT: THE SHOWER FAUCET IS NOT SEALED

CAUSE: shower faucet is not sealed.

CORRECTION: applied silicone to shower faucet as needed.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00
Subtotal for Job #9:			30.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: winterize

CORRECTION: bypassed water heater, drained all holding tanks, ran a.f. through lines and fixtures.

Labor



Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Parts Total:	179.65
Labour Total:	750.00
Sublet Total:	0.00
Extras Total:	170.97
WORK ORDER TOTAL:	1,100.62

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 20 Oct 2022

W/O: 68465
Promised Date: 30 SEP 22



Customer #: 1000
BASDENS AMERICAN RV,

