

aim: C321101

Non-Warranty Goodwill Adjustment

Last Modified by ambri

Item Reference no.

Repair start date Repair date VIN

Pre-auth

Dealer Repairing dealer name

Labor rate Changed Type

Date of Purchase

213701 6845

9/14/2022 9/14/2022

4YDT31R20K7243331

1194 Basden's American RV

150.00

0.00 SA21-414 3/26/20

600 E Baseline Rd
Evansville, IN 47725

Item Name

Quantity Qty Returned Dealer price Markup

Part total

Appr Freight Sub Freight

Sublet

Status

696405 Regulator - Recall Only Kit - A

1.00

0.00

25.00 15.00

28.75

0.00

0.00

0.00

Approved

18749

Component Model: 6020

Component Serial Number: N 18 01

Operation Description

Srvc advisory

Sub hours Apvd Hours

Labor amt

Sublet

Qty Base Hours

Status

7141442B Safety Advisory 21-414 Winn-Tec

0.50

0.50

75.00

0.00

1

0.50

Approved

Complaint: KEYSTONE SAFETY ADVISORY LP

REGULATOR RECALL #21-414

5218749

SECTION: 71 COMPONENT: 414

OPERATION: 7141442B

Cause: RECALL

Correction: TOOK PICTURES OF LP REGULATOR

GOT WITH BEN FOR NEW LP REGULATOR.

REMOVED AND REPLACED LP REGULATOR

WITH NEW THEN CHECKED FOR LP LEAKS

NONE WAS FOUND

(Deking/KRV)

Submitted parts & sublet 28.75

Submitted labor & sublet 75.00

Submitted freight: 0.00

Tax: 0.00

Total Submitted: 103.75

Approved parts & sublet 28.75

Approved labor & sublet 75.00

Approved freight: 0.00

Tax: 0.00

Total approved: 103.75