

e-Authorization

9/22/20
12:47:24 PM

3-Authorization number PA03254105 Reference no: 68547
 Address
 Address

Status: Approved
 VIN

Approved by samya
 Retail sold on

Approved date 9/21/2022

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGS2XP2501577					
Item	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1102816A Brakes, Wiring	0.00	0.50	0.50		1	0.30	Complaint:CHECK BRAKES NOT WORKING WHEN TRAVELING HERE WITH IT Cause:CHECK BRAKES NOT WORKING WHEN TRAVELING HERE WITH IT Correction:CHECKED WIRES AT FRONT DRIVER SIDE IN UNDERBELLY AND FOUND WIRES CAME APART,PUT 3 WIRES BACK TOGETHER AND CRIMPED, TAPED UP UNDERBELLY AND THEY WORK FINE NOW.
2	4123302B Refrigerator - Don	0.00	0.40	0.40		1	0.50	Complaint:FRIDGE DOOR WILL NOT OPEN ALL THE WAY Cause:FRIDGE DOOR WILL NOT OPEN ALL THE WAY Correction:TOOK BOTTOM OF BRACKET ON REF AND TOOK OUT SCREWS AND MOVED REF OVER SO DOOR WOULD NOT HIT WALL, SECURED REF BACK IN PLACE. KRV – REPAIR ONLY approved.
3	6104215A Shower/Tub - Dra	0.00	0.30	0.30		1	0.50	Complaint:SHOWER DRAIN IS LEAKING Cause:SHOWER DRAIN IS LEAKING Correction:TOOK DRAIN PIPE OFF AND SCREWED IT BACK ON STRAIGHT AND BOTTOM PIPE AND TESTED AND IT IS GOOD.
4	3200116A Door - Interior Hin	0.00	0.40	0.20		1	0.20	Complaint:BATHROOM DOOR SHOWER HOLDER WILL NOT STAY IN TRACK Cause:BATHROOM DOOR SHOWER HOLDER WILL NOT STAY IN TRACK Correction:MOVED HOLDER SO DOOR WOULD NOT COME OUT.
5	3300206B Blind - Venetian -	0.00	1.00	0.20		1	0.20	Complaint:BLIND NEXT TO RECLINER IS BROKEN Cause:BLIND NEXT TO RECLINER IS BROKEN Correction:NEED TO R&R BLIND

KRV - Labor time approved in accordance with Keystone RV's flat rate manual.

paper claims only use one pre-authorization number per warranty claim for
 multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

Pre-Authorization

9/22/20
12:47:24 PM

Job Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
6 6109315A	Holding Tank Flush	0.00	0.50	0.30		1	0.20	VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only) Cause:BLACK TANK FLUSH NOT HOOKED UP Correction:CLEANED UP WATER AND FOUND THE LINES THAT WERE NOT HOOKED UP,HOOKED UP LINES AND CLAMPED IT AND IT TESTED FINE.
Pre-Authorization number PA03254105				1.90				

For paper claims only, use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the