

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 1251636 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CAZB5NX025726 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 205 / 205 ITEM # ACAT343BHTSLE DEALER RO # 68602 CLAIM START DATE 09/26/2022 CLAIM END DATE 01/01/1900	
Labor rate: \$150.00 OWNER INFORMATION JOSHUA D. JOHNSON 2703 E 600 S Fort Branch, IN 47648 USA		
Retail Date of Purchase 05/07/2022	WARRANTY EXPIRATION DATE 05/07/2023	

Claim Line Details

Labor

Line# 1	Operation Code 20-46-01-13-000730 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-09-26 12:29:58 :: 2 WINDOWS ON THE DRIVERS SIDE THE SEALS ARE COMING OUT gimp is pulling out of corners of windows, SHRINKING in sun gimp is pulling out of corners of windows, pull gimp back to loose places and install in window, fill open spots at ends with silicone Additional Note : bhoffman@americanrvcenter.com, 2022-09-26 12:30:51 :: THERE ARE 2 WINDOWS	Operational Description Window Glazing, Seal - Exterior/Windows/Replace/Visibility	
	Model # Serial #	Dlr Sub Hrs 0.60 Appr Hrs 0.60	Sub Labor Amt \$90.00 Appr Labor Amt \$90.00
	Notes AUTHORIZED AS REQUESTED FOR TWO WINDOWS		

Labor

Line# 2	Operation Code RC-026-01-00-004186 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-09-26 12:31:26 :: RECALL 22V243 LP QUICK CONNECT INSPECT AND CHANGE 2 QUIK DISCONETS THERE ARE 2 QUICK CONNECTS	Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code	
	Model # Serial #	Dlr Sub Hrs 0.60 Appr Hrs 0.60	Sub Labor Amt \$90.00 Appr Labor Amt \$90.00
	Notes AUTHORIZED AS REQUESTED FOR TWO QUICK DISCONNECTS		

Labor

Line# 3	Operation Code RC-003-22-00-004205 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-09-26 12:32:34 :: JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL inspect breakaway wiring, wired wrong cut under belly, dig through foam insulation to find breakers, remove breakaway wire from breaker and wire to battery side of disconnect, seal up under belly	Operational Description 22V477, 2022-358 - BREAKAWAY SWITCH WIRING - INSPECT AND REWIRE - Recall/Electrical/Rewire/No Tread Code	
	Model # Serial #	Dlr Sub Hrs 0.30 Appr Hrs 0.30	Sub Labor Amt \$45.00 Appr Labor Amt \$45.00

Notes

Submitted

Labor Amt	\$225.00
Parts & Freight	\$0.00
Total	\$225.00

Approved

Labor Amt	\$225.00
Parts & Freight	\$0.00
Total	\$225.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.