



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68606
Promised Date: 30 SEP 22

CUSTOMER WORK ORDER

WO #: 68606

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: P.HUNT
Location: 0926 BH TO CLOSE

Stock #: 11141
Stock Desc: 2022 5W KEYSTONE
COUGAR 316RLS
Chassis #: 4YDFCGR24P2501614
Serial #: 4YDFCGR24P2501614
Mileage: 0
Licence:

Invoice #:
Date In: 21 SEP 22
Promised: 30 SEP 22
Date Sched:
Completed: 27 SEP 22
Warr. Date:

Job #PDINFW - Internal

PDI - NEW FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR HITTING LATCH

CAUSE: ENTRY DOOR HITTING LATCH DUE TO STRIKING PLATE NOT BEING ATTACHED PROPERLY

CORRECTION: ATTACHED STRIKING PLATE

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00

Subtotal for Job #1: 30.00

Job #2 - Warranty

COMPLAINT: PANTRY DOOR IN BEDROOM HITTING FRAME

CAUSE: PANTRY DOOR WAS HIITING FRAME BECAUSE HINGES WERENT ALL THE WAY IN

CORRECTION: TIGHTEBNED UP HINGES

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



Z990 MISCELLANEOUS REPAIR RAB 30.00

Subtotal for Job #2: 30.00

Job #3 - Warranty

COMPLAINT: VENT IN LIVING ROOM WONT OPEN

CAUSE: VENT IN LIVING ROOM WONT OPEN AT CONTROL BOARD DUE TO WIRE BEING UNPLUGGED FROM THE FACTORY

CORRECTION: CONNECTED WIRE AND TESTED FOR FUNCTION

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	60.00

Subtotal for Job #3: 60.00

Job #4 - Warranty

COMPLAINT: IN-COMMAND CONTROL BOARD SHUTS DOWN RANDOMLY

CAUSE: IN COMMAND CONTROL BOARD RANDOMLY SHUTS OFF DUE TO PLUGS NOT BEING ALL THE WAY ATTACHED

CORRECTION: ATTACHED PLUGS AND TESTED

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00
Z990	MISCELLANEOUS REPAIR	RAB	0.00
Z990	MISCELLANEOUS REPAIR	RAB	0.00

Subtotal for Job #4: 30.00

Job #5 - Warranty

COMPLAINT: BEDROOM DRAWER NOT SHUTTING GETTING STUCK

CAUSE: BEDROOM CABNIET DRAWER WOULDNT SHUT BECAUSE THE SCREW THAT HOLDS THE RAIL HAD COME LOSE FROM CABNIET CAUSING DRAWER TO HIT SCREW AND NOT SLIDE ON TRACK PROPARLY

CORRECTION: RE ATTACHED SCREW AND RAIL

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	30.00

Subtotal for Job #5: 30.00

Parts Total: 0.00
Labour Total: 180.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 180.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 68606
Promised Date: 30 SEP 22



Customer #: 1000
BASDEN'S AMERICAN RV,

