

Authorization number PA03267373 Reference no: 68630 Status: Approved Approved by papca Approved date 10/4/2022
Billing name Address VIN Retail sold on

Basden's American RV
Basden's American RV
600 E Baseline Rd
Evansville, IN 47725
4YDTGGM21PL500604

Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	32018084 Decorative Wood	0.00	0.10	0.10		1	0.10	Complaint:STAPLES NEED TO BE SET AND WOOD FILLER ADDED TO COMBINE NEXT TO ENTRY DOOR,
								Cause:STAPLES HANGING OUT Correction:set staples so they were flush and filled in with wood putty KRV – REPAIR ONLY approved.
2	5104316A Receptacle - 120V	0.00	0.30	0.20		1	0.20	Complaint:THE WIRE LOOM IS HANGING UNDER THE REAR BUMPER
								Cause:I PUT THE WIRE BACK IN THE PLASTIC SLEVE AND PUT BLACK ELE. TAPE AROUND IT SO IT WOULDNT COME BACK OUT Correction:I PUT THE WIRE BACK IN THE PLASTIC SLEVE AND PUT BLACK ELE. TAPE AROUND IT SO IT WOULDNT COME BACK OUT KRV – REPAIR ONLY approved.
3	4131914B Water Heater - St	0.00	0.20	0.30		1	0.30	Complaint:THE WATER HEATER DOOR IS OFF
								Cause:NOT INSTALL RIGHT Correction:REINSTALLED WATER HEATER DOOR 2 SCREWS WERE MISSING I FOUND REPLACEMENT SCREWS FOR THE DOOR KRV – REPAIR ONLY approved.
4	4154006B Water Heater - Ta	0.00	0.20			1	1.00	Complaint:THE WATER HEATER LATCH IS INOPERATIVE
								Cause:not installed right Correction:ADJUSTED SPRING AND LATCH KRV - add to line 3
5	3401216A Backsplash - Kitcl	0.00	0.50	0.30		1	0.10	Complaint:THE BACK SPLASH IS LOOSE BEHIND THE KITCHEN SINK
								Cause:BACKSPLASH NOT GLUED

paper claims only use one pre-authorization number per warranty claim for
Please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

e-Authrization

10/5/20
02:34:42

lu Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
6 610401	Shower/Tub - Wal	0.00	0.40	0.40		1	0.50	Correction: GLUED BACKSPLASH BACK TO WALL KRV - REPAIR ONLY approved. Complaint: THE SHOWER SURROUND NEEDS TO BE SILICONED Cause: SHOWER SURROUND WAS NOT SEALED AND LEAKING Correction: SILICONED THE SHOWER SURROUND KRV - REPAIR ONLY approved.
3-Authoriza				1.30				

paper claims ~~only~~ use one pre-authorization number per warranty claim for
 ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the