

e-Authorization

10/12/20
12:18:34

3- Authorization number PA03266161 Reference no: 68676 Status: Approved Approved by steic Approved date 10/6/2022
 rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTSGL28N3108527
 600 E Baseline Rd
 Evansville, IN 47725

Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2100803B Floor - Decking - I	0.00	0.75	0.50		1	0.50	Complaint:TOP BUNK WOOD IS CRACKED UNDER CUSHION Cause:FOUND UNIT HAD DAMAGE Correction:took pictures, took out plywood and took out staples and put another piece and staples in place Complaint:TOP TWO ROWS OF ALUMINUM HAVE POPPED LOOSE ON ODS Cause:STAPLES CAME LOOSE FROM THE METAL AND BLEW OUT AND IS GETTING CLOSE TO DAMAGED Correction:WILL HAVE TO REMOVE FRONT BED WINDOW, WILL HAVE REMOVE THE COUCH WINDOW, WILL HAVE TO REMOVE THE SINK WINDOW, WILL HAVE TO REMOVE THE STOVE VENT, BOTH FRONT AND REAR CORNER MODINGS WILL HAVE TO COME OFF,BEFORE WE CAN FIX THE METAL,
2	2102716A Wall - Metal Sidin	0.00	14.00	13.65		1	0.50	

KRV - This can be repaired top down - time approved per flat rate

Qty	Hours	Sub operation	Description
1	0.20	2202308J	Range Vent - Remove, Seal & Rein
1	1.00	2315008J	Window - 47" or Less - Complete
1	1.00	2315008J	Window - 47" or Less - Complete
1	1.00	2315008J	Window - 47" or Less - Complete
	14.15		

3- Authorization number PA03266161

r paper claims only use one pre-authorization number per warranty claim for
 ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the