

**aim Response**

10/11/2022  
09:52:29 am

aim: C3235078 **Non-Warranty Goodwill Adjustment** Last Modified by: ambri

aim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date of Purchase
235078	68754	10/6/2022	10/6/2022	4YDDT28223M3102379	1194	Basden's American RV	600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	7/30/20

Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

Problem listed below.  
15108  
Component Model: 6020  
Component Serial Number: N20 17

Operation	Description	Srvc advisory	Sub hours	Apv'd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION: 71 COMPONENT: 414 OPERATION: 7141442B Cause: LP REGULATOR RECALL MEETS RECALL Correction: INSTALLED NEW LP REGULATOR AND TESTED (Deking KRV)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & sublet	28.75	Approved parts & sublet	28.75
Submitted labor & sublet	75.00	Approved labor & sublet	75.00
Submitted freight	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
<b>Total Submitted:</b>	<b>103.75</b>	<b>Total approved:</b>	<b>103.75</b>