

aim Response

10/13/2022
03:06:59 pm

aim: C3239194

Non-Warranty Goodwill Adjustment

Last Modified by: ambrl

Item Reference no.

Repair start date

Repair date VIN

Pre-auth

Dealer Repairing dealer name

Labor rate

Changed Type warranty rate

Date Of Purchase

239194 68799

10/11/2022 10/11/2022 4YDT30126L3104416

1194 Basden's American RV
600 E Baseline Rd
Evansville, IN 47725

150.00

0.00 SA21-414 7/7/2022

Item Name

Quantity Qty Returned

Dealer price Markup

Part total

Appr Freight

Sub Freight

Sublet

Status

696405 Regulator - Recall Only Kit - A

1.00

0.00

25.00

15.00

28.75

0.00

0.00

0.00

Approved

18749

Component Model: 6020

Component Serial Number: N 19 04

Operation Description

Srvc advisory

Sub hours Apvd Hours

Labor amt

Sublet

Qty Base Hours

Status

7141442B

Safety Advisory 21-414 Winn-Tec
Complaint: KEYSTONE SAFETY ADVISORY LP
REGULATOR RECALL #21-414
SECTION: 71 COMPONENT: 414
OPERATION: 7141442B
Cause: LP REGULATOR RECALL
Correction: INSTALLED NEW LP REGULATOR
AND TESTED

0.50

0.50

75.00

0.00

1

0.50

Approved

(Deking/KRV)

Submitted parts & sublet 28.75
Submitted labor & sublet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 103.75

Approved parts & sublet 28.75
Approved labor & sublet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 103.75