

e-Authorization

10/28/20
05:42:14

3-Authorization number PA03289642 Reference no: 68825 Status: Approved Approved by samya Approved date 10/27/2022
Billing Name Address VIN Retail sold on

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGR29N2504733	10/13/2022					
	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3200114F	Door - Interior Hin	0.00	0.20	0.20		1	0.10	Complaint:BATHROOM DOOR WILL NOT LATCH CLOSED Cause:BATHROOM DOOR WILL NOT LATCH CLOSED. Correction:Latch place mounted too low. Removed latch plate, cutout hole in door frame to raise latch plat. Remounted latch plate in new holes. Checked operation of door. Door now closes and latches closed.
2	3201806A	Decorative Wood	0.00	0.20	0.20		1	0.10	Complaint:TRIM IN BUNK ROOM LOOSE Cause:TRIM IN BUNK ROOM LOOSE. Correction:Door frame trim and wall panel loose on hinge side of door. Trim too long and bowed out. Removed door frame trim and cut off at bottom ti fit. Secured wall panel on edge to wall stud. Remounted door frame trim and filled all nail holes with putty.
3	6104016A	Shower/Tub - Wal	0.00	0.20	0.20		1	0.50	Complaint:THE SHOWER SURROUND IS LOOSE ON THE EDGE Cause:THE SHOWER SURROUND IS LOOSE ON THE EDGE. Correction:Shower surround is loose and bowed on edge. Added plastic push rivets to edge inbowed area. Resealed edge of shower surround with clear silicone.
-Authorization number PA03289642					0.60				

paper claims only use one pre-authorization number per warranty claim for
multiple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the