

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68989
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 5098 - OTTIS D. PUTLER
Address: 2535 W. BOONVILLE-NEW HARMONY RD. EVANSVILLE, IN

47720

Phone: 812-449-8281

Stock Number: 10833 - 2022 CHEROKEE GREY WOLF 23MK 4X4TCKY28NK082426

VIN: 4X4TCKY28NK082426 HIN: SER#: 4X4TCKY28NK082426

Mileage: 0 Work Order Comp: 16 NOV 22

Auth. No: Dealer #:

Warr. Date: 03 JUN 22 Work Order Date: 19 OCT 22 Inv #: 385403

WO # Job # Description JOB INFORMATION *****

68989 2 SLIDE ROOM MOTORS SEEM LIKE THEY ARE WORKING HARDER THAN THEY SHOULD. SKIPS ALONG SOMETIMES AS IT COMES IN TESTED MOTOR AND CABLE AND THEY ARE GOOD, DID OVERRIDE ON BOX AND IT WILL STILL NOT COME OUT SOMETHING IN RAIL IS HOLDING IT UP, WONT KNOW WHAT UNTIL I TAKE APART. PULLED ENTIRE SYSTEM APART AND INSTALLED NEW HAD TO DRILL NEW HOLES AND MEASURE SYSTEM BECAUSE IT WAS THE OLDER SYSTEM AND THE SYSTEM ON THE TRAILER WAS INVERTED. I THEN SEALED AND REMOUNTED THE CONTROL BOARD UNDER THE ROOM.

68989 1 ENTRY DOOR DONT LOCK RIGHT, STRIKER PLATE IS REMOVED AND LAYING ON THE COUCH
PUT STRIKER PLATE BACK ON AND ADJUSTED.

68989 3 THE BRACKET THAT HOLD THE BED UP ARE BROKEN
TOOK OFF HINGE BECAUSE IT IS BROKEN, INSTALLED SHOCKS BACK IN PLACE, CRAIG IS GETTING PARTS. OTHER HINGE WAS BENT ALSO, I INSTALLED 3 HINGES FOR MORE SUPPORT, REINSTALLED SHOCKS.

68989 4 WOOD PANEL BELOW COUNTER NEAR FRIDGE/STOVE HAS COME LOOSE
HAD TO TAKE OFF FURNANCE COVER AND TAKE OUT CONVERTER TO GET TO BACK SIDE OF PANEL TO REATTACH, ALSO FOUND VENT TUBE WAS OFF OF FURNANCE REATTACHED TUBE TO FURNANCE AND PANEL AND PUT CONVERTER BACK IN.

68989 5 STOVE COVER HINGE HAS POPPED LOOSE

