

aim : C3248299 Non-Warranty Goodwill Adjustment Last Modified by:ambrl

aim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
248299	69008	10/21/2021	10/21/2022	4YDT27428K3100003		1194 Basden's American RV 600 E Baseline Rd Evansville, IN 47725		150.00	0.00	SA21-414	2/9/201

Item #	Item Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
		1.00	0.00	0.00	15.00	0.00	0.00	0.00	0.00	Approved

rshall in unit

Operation #	Description	Srvc advisory	Sub hours	Apvcd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442K	Safety Advisory 21-414 Winn-Tec Complaint: LP REGULATOR RECALL 21-414 Cause: DOES NOT NEED TO BE REPLCAED Correction: took pictures and regulator dosent need replaced.		0.30	0.30	45.00	0.00	1	0.30	Approved

Submitted parts & sublet :	0.00	Approved parts & sublet :	0.00
Submitted labor & sublet :	45.00	Approved labor & sublet :	45.00
Submitted freight :	0.00	Approved freight :	0.00
Tax:	0.00	Tax:	0.00
Total Submitted :	45.00	Total approved :	45.00