

Pre-Authorization

10/27/20
11:13:25

Pre-Authorization number PA03289484 Reference no: 69020 Status: Approved Approved by rodgmn Approved date 10/26/2022
Technician Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDFM0R28N4702082 3/10/2022
600 E Baseline Rd
Evansville, IN 47725

Job Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
2 2106906A	Slide Out - Resize	0.00	2.50	2.50		1	0.50	Complaint:SLIDE ROOM ON DOOR SIDE IS MAKING A NOISE WHEN GOING IN AND OUT Cause:check slideroom hydraulics found 3 1/2 quarts of fluid low, fill to full, run room and lube works, traced sound to the shaft treads moving through the bracket Correction:check slideroom hydraulics found 3 1/2 quarts of fluid low, fill to full, run room and lube works, traced sound to the shaft treads moving through the bracket, cut underbelly and check mounting for cylinder, need to hone hole too give room for movement, disconnect shaft from room slide, file burs off and use a flap wheel to hone hole, connect shaft back up test and adjust room, use under belly tape to tape up underbelly,

Pre-Authorization number PA03289484

Qty	Hours	Sub operation	Description
1	0.50	1201112A	Enclosed Underbelly Panel
1	1.50	2103118A	Slide Out - Box - Remove and Reinstall
	2.50		

This paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the