

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69027
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52273 - JUSTIN L. BULLARD
Address: 5 VICTORY LN FAIRFIELD, IL

62837

Phone: 618-516-3017

Stock Number: 10646 - 2022 CATALINA 263BHCKLE 5ZT2CARB3NU039464

VIN: 5ZT2CARB3NU039464 HIN:

SER#: 5ZT2CARB3NU039464

Mileage: 0

Work Order Comp: 16 NOV 22

Auth. No:

Dealer #:

Warr. Date: 12 FEB 22

Work Order Date: 21 OCT 22

Inv #: 385420

WO # Job # Description JOB INFORMATION

69027 3 CHECK GAPS ON EACH LOWER CORNER OF THE SLIDE ROOM WHEN IT IS IN
OR OUT. HE BELIEVES THAT A PART OF THE SEAL MIGHT HAVE COME OFF.
CHECK GAPS ON EACH LOWER CORNER OF SLIDE ROOM WHEN IT IS IN OR
OUT. CUSTOMER BELIEVES THAT A PART OF THE SEALMIGHT HAVE COME
OFF.
Checked lower flap seals. Seals are being pulled in under slide
room when running room in and tearing flap seals. 10/24/2022:
Turned in parts request for new flap seals. Received new flap
seals. Removed bottom corner seals. Replaced damaged flap on
corner pieces. Installed new flap seal on both pieces. Cut off
flap on old seal that would flip in when slide out is ran in.
Cut to length new flap seal. Stapled new flap seal in place.
Added metal strip over mounting of flap seal to secure in place.
Remounted corner seals to close up corner gap. Remounted wire
support. Checked operation of slide out several times. New flap
seal not rolling under slide out. Moved unit to service
completed area. HELPED DAVE PUT ON SEAL

69027 2V243 RECALL 22V243 LP QUICK CONNECT
22V243 - RECALL 22V243 LP QUICK CONNECT.
Moved unit into shop from service lot. Checked Quick Connect for
Recall part. Quick connect is affected recall part. Removed
quick connect part. Cleaned threads per recall instructions.
Applied thread seal and installed new part. Performed 3 min.
drop test. No leaks.

Claim : 69027

 WO # Job # Description JOB INFORMATION

 69027 BRAKE JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL
 BRAKE - JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL.
 Removed all tape around factory cut hole in underbelly. Removed
 brake-away switch from frame mounting. Took picture of back of
 switch and brake-away wire going to small breaker. Cut wire off
 at terminal. Rerouted wire to battery side of disconnect switch.
 Installed new ring terminal. Removed nut on disconnect switch
 and installed wire from brake-away switch. Reinstalled nut on
 back of switch and tightened. Remounted brake-away switch on
 frame. Sealed up hole in underbelly with underbelly tape.

 Part No Job# Description PARTS Qty Price Total

 C01249768 3 SINGLE WIPER SEAL 3.00 1.92 5.76
 BRV111994 3 ANGLE FLAP SEAL-BLACK - KEYSTONE 14.00 0.78 10.92

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.91 150.00 136.50
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.02 150.00 3.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.07 150.00 10.50
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 V243 MISC LABOUR CODE (EXTERNAL) 1.00 150.00 150.00
 Z990 RAKE MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00
 Z990 0.30 150.00 45.00

 Excode Job# Description EXTRAS Qty Price Total

 SS 3 SHOP SUPPLIES 1.00 0.00 0.00
 FRT 3 UPS- SEAL 1.00 17.34 17.34
 FRT 3 UPS-SEAL 1.00 15.96 15.96

Parts Total: 16.68
 Labour Total: 390.00
 Sublet Total: 0.00
 Extras Total: 33.30

>>>> Claim Total: 439.98

Customer Signature: _____

Date: _____