

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69040
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 27854 - JASON MILHEISER
Address: 9414 ASHWORTH DR EVANSVILLE, IN

47725

Phone: 812-480-0722

Stock Number: 11050 - 2022 FREEDOM EXPRESS 326BHDSLE 5ZT2FEYB2NW022384

VIN: 5ZT2FEYB2NW022384 HIN: SER#: 5ZT2FEYB2NW022384

Mileage: 0

Work Order Comp: 14 NOV 22

Auth. No:

Dealer #:

Warr. Date: 15 JAN 22

Work Order Date: 24 OCT 22

Inv #: 385322

WO # Job # Description JOB INFORMATION

69040 4 CUSTOMER GETS WATER IN THE CAMPER FROM THE VENT ABOVE THE STOVE
checked the outside vent and found a crack in the factory sealer
that was used. fixed the crack with clear silicone. sprayed water
to check for leaks. FOUND THAT THE WINDOW WAS LEAKING, THE SEAL
IS NOT STICKING TO THE FRAME AS IT SHOULD.

69040 2V243 RECALL 22V243 LP QUICK CONNECT KEYS WILL BE IN THE WATER HEATER
COMPARTMENT
REMOVED AND PLACED THE LP QUICK DISCONNECT

69040 2 ONE OF THE SEAMS/STICHING IS SPREADING APART IN ONE OF THE
RECLINERS THE LEFT AS YOU LOOK AT IT
TOOK PICTURES AND PO SHEET FOR BEN WARRANTY

69040 3 THE FRONT A/C WAS NOT COOLING PROPERLY DURING THIS SUMMER'S
CAMPING SEASON.
pulled down the ceiling control to ac to run a amp draw. couldnt
get an amp draw because then ac shut off. then tried to run
another amp drwa again. at that time had seen sparks from the
plug. the plug from ac to control box was not seated causing the
ac compressor to run.if wires got bumped then the ac would stop
running. the plug from ac to control box will not plug in proper
had denny and ben advise this problem. put in po for warranty on
the control box ceiling mount. check pictures

Part No Job# Description PARTS Qty Price Total

AMZ.215X.375S 4 SMALL "D" SEAL .215 X .375 6.00 0.55 3.30

Claim : 69040

```

*****
Part No      Job#  Description          PARTS          Qty      Price      Total
*****
509023       4    Garage - Door - Bulb Seal - Wide  7.00      0.72      5.04

```

```

*****
Lab Code     Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990         4    MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00
Z990         4    MISC LABOUR CODE (EXTERNAL)          0.30     150.00     45.00
Z990        V243  MISC LABOUR CODE (EXTERNAL)          0.61     150.00     91.50
Z990         2    MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00
Z990         2    MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00
Z990         3    MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00
Z990         3    MISC LABOUR CODE (EXTERNAL)          0.50     150.00     75.00
Z990         3    MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00
Z990         3    MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00
Z990         3    MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00

```

```

*****
Job#  Sublet Description          SUBLET          Total
*****
2    FURNITURE REPAIR

```

```

Parts Total:      8.34
Labour Total:     211.50
Sublet Total:     250.00
Extras Total:      0.00

```

>>>> Claim Total: 469.84

Customer Signature: _____

Date: _____