



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69040

CUSTOMER WORK ORDER

WO #: 69040 (Appointment Date: 24 OCT 2022 - Time: 07:00am)

Customer: 27854 - MILHEISER, JASON Stock #: 11050

- 812-480-0722

Tag:

Author: BJ.WRIGHT

Location: 1115 CHECK WORK

Stock Desc: (11050) 2022

COACHMEN FREEDOM EXPRESS

326BHDSLE

Chassis #: 5ZT2FEYB2NW022384

Serial #: 5ZT2FEYB2NW022384

Mileage:

Licence:

Invoice #:

Date In: 24 OCT 22

Promised:

Date Sched:

Completed: 14 NOV 22

Warr. Date: 15 JAN 22

Job #22V243 - Warranty

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

KEYS WILL BE IN THE WATER HEATER COMPARTMENT

CORRECTION: REMOVED AND PLACED THE LP QUICK DISCONNECT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	91.50

Subtotal for Job #22V243: 91.50

Job #2 - Warranty

COMPLAINT: ONE OF THE SEAMS/STICHING IS SPREADING APART IN ONE OF THE RECLINERS
THE LEFT AS YOU LOOK AT IT

CORRECTION: TOOK PICTURES AND PO SHEET FOR BEN WARRANTY

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Sublet

Description	Total
FURNITURE REPAIR	250.00

Subtotal for Job #2: 250.00

Job #3 - Warranty

COMPLAINT: THE FRONT A/C WAS NOT COOLING PROPERLY DURING THIS SUMMER'S CAMPING SEASON.

CORRECTION: pulled down the ceiling control to ac to run a amp draw. couldnt get an amp draw because then ac shut off. then tried to run another amp drwa again. at that time had seen sparks from the plug. the plug from ac to control box was not seated causing the ac compressor to run.if wires got bumped then the ac would stop running. the plug from ac to control box will not plug in proper had denny and ben advise this problem. put in po for warranty on the control box ceiling mount. check pictures

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	75.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Customer #:
27854



Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #3: 75.00

Job #4 - Warranty

COMPLAINT: CUSTOMER GETS WATER IN THE CAMPER FROM THE VENT ABOVE THE STOVE

CORRECTION: checked the outside vent and found a crack in the factory sealer that was used. fixed the crack with clear silicone. sprayed water to check for leaks. FOUND THAT THE WINDOW WAS LEAKING, THE SEAL IS NOT STICKING TO THE FRAME AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	45.00

Parts

Part #	Description	Qty	Price	Total
6993	SMALL "D" SEAL .215 X .375	6.00	0.55	3.30
509023	Garage - Door - Bulb Seal - Wide D Shape - 0.563" x 0.75"	7.00	0.72	5.04

Subtotal for Job #4: 53.34

Parts Total:	8.34
Labour Total:	211.50
Sublet Total:	250.00
Extras Total:	0.00
WORK ORDER TOTAL:	469.84

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 Nov 2022

W/O: 69040



Customer #: 27854

