

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1295013
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEUB7PW026729
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET294BHDS-320
		DEALER RO #	69066
		CLAIM START DATE	10/26/2022
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 60-141-19-00-001596	Operational Description Tub Surround - Plumbing/Shower, Tub Surround/Reseal/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-26 17:49:42 :: SHOWER SURROUND NEEDS SEALED SHOWER SURROUND NOT SEALED COMPLETLEY NEEDS SEALED UP SEALED UP SHOWER SURROUND	
	Model #	Dlr Sub Hrs 0.30
	Serial #	Appr Hrs 0.00
		Sub Labor Amt \$45.00
		Appr Labor Amt \$0.00

Notes

shower surround does not get sealed along the top

Labor

Line# 2	Operation Code 60-138-24-00-001535	Operational Description Drainage Lines - Plumbing/Drainage System/Repair/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-10-26 17:51:22 :: THE KITCHEN SINK IS LEAKING NEAR THE DRAIN the kitchen sink was leaking near the lower elbow connector. the connection was not screwed on tight at all causing a leak the kitchen sink was leaking near the lower elbow connector. the connection was not screwed on tight at all causing a leak. tightened connector and tested	
	Model #	Dlr Sub Hrs 0.30
	Serial #	Appr Hrs 0.20
		Sub Labor Amt \$45.00
		Appr Labor Amt \$30.00

Notes

tighten fitting

Submitted	Labor Amt	\$90.00	Approved	Labor Amt	\$30.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$90.00		Total	\$30.00

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____

DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.