

# FOREST RIVER WARRANTY CLAIM FORM

|                         |            |                          |                   |
|-------------------------|------------|--------------------------|-------------------|
| DEALER ACCOUNT #        | 0005106    | CLAIM STATUS             | Authorized        |
| BASDEN RV CENTER INC    |            | CLAIM                    | 1292992           |
| DBA AMERICAN RV CENTER  |            | CLAIM ORIGIN             | WEB               |
| 600 E BASELINE ROAD     |            | ORIGINAL CLAIM ID        |                   |
| EVANSVILLE, IN 47725    |            | VIN                      | 5ZT2CAXB5NX023347 |
| USA                     |            | CHASSIS VIN              |                   |
|                         |            | MILEAGE                  | 0                 |
| Labor rate:             | \$150.00   | SITE/WAREHOUSE           | 205 / 205         |
| OWNER INFORMATION       |            | ITEM #                   | ACAT323BHDSCCKLE  |
| BENJAMIN A MILLAY       |            | DEALER RO #              | 69070             |
| 9169 JACK HINTON RD     |            | CLAIM START DATE         | 10/25/2022        |
| Philpot, KY 42366       |            | CLAIM END DATE           | 01/01/1900        |
| USA                     |            |                          |                   |
| Retail Date of Purchase | 11/15/2021 | WARRANTY EXPIRATION DATE | 11/15/2022        |

## Claim Line Details

### Labor

|                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                                       |                                                                                                                                                      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|
| Line# 1                                                                                                                                                                                                                                                                                                                                                                                                                                                       | Operation Code<br>RC-026-01-00-004186 | Operational Description<br>22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code |
| Complaint, Cause, Correction<br>Original Note : bhoffman@americanrvcenter.com, 2022-10-25 16:58:56 :: RECALL 22V243 LP QUICK CONNECT 22V243 - RECALL 22V243 LP QUICK CONNECT. Checked LP quick connect for recall. Connector has "ENERCO GROUP" on side of slider. Removed Lp quick connector. Cleaned threads on brass barb fitting. Applied gas thread sealant to threads. Installed new LP quick connector. Performed LP drop test for (3) Mins. No leaks. |                                       |                                                                                                                                                      |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                               | Model #                               | Dlr Sub Hrs      0.30      Sub Labor Amt    \$45.00                                                                                                  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                               | Serial #                              | Appr Hrs          0.30      Appr Labor Amt    \$45.00                                                                                                |

Notes

### Labor

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                       |                                                                                                                                     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|
| Line# 2                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | Operation Code<br>RC-003-22-00-004205 | Operational Description<br>22V477, 2022-358 - BREAKAWAY SWITCH WIRING - INSPECT AND REWIRE - Recall/Electrical/Rewire/No Tread Code |
| Complaint, Cause, Correction<br>Original Note : bhoffman@americanrvcenter.com, 2022-10-25 17:00:18 :: JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL BRAKE - JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL. Cut hole in underbelly for access to terminal block. Had to dig out all of spray foam that covered wires and terminal block. Removed brake away power wire from terminal block. Removed battery disconnect switch from frame mount. Added ring terminal to wire and connected to cable from battery. Remounted disconnect switch on frame. Checked operation of brake-away switch after recall. OK. Added underbelly tape to seal up hole that was cut in underbelly. |                                       |                                                                                                                                     |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Model #                               | Dlr Sub Hrs      0.30      Sub Labor Amt    \$45.00                                                                                 |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Serial #                              | Appr Hrs          0.30      Appr Labor Amt    \$45.00                                                                               |

Notes

|                  |                 |         |                 |                 |         |
|------------------|-----------------|---------|-----------------|-----------------|---------|
| <b>Submitted</b> | Labor Amt       | \$90.00 | <b>Approved</b> | Labor Amt       | \$90.00 |
|                  | Parts & Freight | \$0.00  |                 | Parts & Freight | \$0.00  |
|                  | Total           | \$90.00 |                 | Total           | \$90.00 |