



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69124

CUSTOMER WORK ORDER

WO #: 69124 (Appointment Date: 01 NOV 2022 - Time: 07:00am)

Customer: 50416 - REYNOLDS, TIM -
270-993-1526

Tag:

Author: BJ.WRIGHT

Location: 1109 CHECK STATUS WITH
DW

Stock #: 10589

Stock Desc: 2021 TT KEYSTONE
COUGAR HALF-TON 29FKD

Chassis #: 4YDT29F29MV502385

Serial #: 4YDT29F29MV502385

Mileage: 0

Licence:

Invoice #: 385153

Date In: 29 OCT 22

Promised:

Date Sched:

Completed: 10 NOV 22

Warr. Date: 29 AUG 20

Job #1 - Warranty

COMPLAINT: 22-430 OUTRIGGERS

CORRECTION: IT DOES NEED THE OUTRIGGER RECALL THERE IS ONLY A 2 INCH SPACE BETWEEN OUTRIGGER AND TIRE . I GAVE MATT THE INFO TO ORDER 2 BOLT ON OUTRIGGERS

i inspected the tires for any damage, no visable damage.removed finders, removed tires. i cut a notch in the outriggers with a grinder with a cut off disk. i spray painted the bear metal with black paint. in between the wheels i installed the new bolt on outriggers with hardware advised by the recall sheet. put tires back on uni reinstalled the finders and siliconed them. i checked the tire pressure they all were very low. inflated the tires to 80 psi

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	75.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	75.00

Parts

Part #	Description	Qty	Price	Total
501127	FRAME - OUTRIGGER - KEYSTONE	2.00	17.30	34.60

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
FRT	UPS-OUTRIGGERS	1.00	16.93	16.93

Subtotal for Job #1: 201.53

Job #2 - External

COMPLAINT: CUSTOMER COULD NOT GET UNIT TO LEVEL ON HIS LAST OUTING. CUSTOMER GOT LEFT FRONT JACK ERROR ON LEVELING SYSTEM. CUSTOMER WAS PLUGGED IN

CORRECTION: I CYCLED THE LEVELING SYSTEM 4 TIMES AND DID NOT GET A LEFT FRONT JACK CODE?
CODE WAS MOST LIKELY CAUSED BY TEMPORARY LOW VOLTAGE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #2: 0.00



Customer #: 50416
REYNOLDS, TIM

Job #3 - External

COMPLAINT: DINING WINDOW HAS WATER STAIN AND THERE IS MOLD ON THE CARPET UNDER THE WINDOW

CORRECTION: THE ROOF TAPE ON SLIDE ROOM HAD COME UNATTACHED WATER WAS COMING IN THROUGH THE FAR RIGHT LIGHT FIXTURE. APPLIED 6' ROOF TAPE. ALONG THE SLIDE ROOM STILL NEEDS WATER TEST

PERFORMED WATER TEST FOR 30 MIN OVER THE ENTIRE SLIDE ROOM AND NO LEAKS.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Parts

Part #	Description	Qty	Price	Total
38-9089	QUICK ROOF EXTREME 6" X 25"	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: ON THE AWNING THE FRONT SHOCK BROKEN AND NEEDS REPLACED

CORRECTION: I GAVE MATT THE INFO FOR ORDERING A NEW SHOCK ARM
REMOVED OLD BROKEN SHOCK. REMOVED SET PINS FOR SHOCK. INSTALLED NEW SHOCK. PUT SET PINS BACK IN

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Parts

Part #	Description	Qty	Price	Total
382268	Awning - Strut - Gas - 124 Lb - For Flat Awning - Lippert	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-STRUT	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Parts Total: 34.60
Labour Total: 150.00
Sublet Total: 0.00
Extras Total: 16.93
WORK ORDER TOTAL: 201.53

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 11 Nov 2022

