



Warranty Authorization Form

Date: 5/11/2023

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 38254

Series: Valor

Notes:

Status: Approved

Unit: 7M5FV453XPA006894

Model: 2023VAL40V13

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725

Requestor: Ben Hoffman

Return Fax #:

Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 14078 SLIDEOUT FASCIA - INTERIOR -
REPLACE

Fault Code: CRACKED

Serial #:

Model #:

Notes: 5/10/23: Danielle -- please change to appropriate flat rate code regarding fascia / where was this located in the coach? 5-10 BH THAT IS THE SLIDE WITH THE DINNETTE SORRY

Problem: WOOD VALANCE ON SLIDE SPLIT

Cause: took of fascia and glue together and let dry, reinstalled fascia and covered holes we have new piece on order.

Remedy: TOOK OFF FACIA AND PULLED OUT STAPLES AND CUT NEW PIECE TO FIT AND INSTALLED BACK IN PLACE AND COVERED NAIL HOLES WITH PUTTY.

Part Return Req: No

Status: Approved

Time Requested: .2

Time Allowed: .2

Sublet Repairs: 0.00

Operation Line 2

Flat Rate Code: 22510 SIDE PATIO - REPAIR (photos required)

Fault Code: PART MISSING

Serial #:

Model #:

Notes:

Problem: BRACKET FOR SLIDING PATIO WALL IS MISSING.

Cause: INSTALLED NEW BRACKET GOT FOUR SCREWS HAD TO PAINT TO MATCH, AND INSTALLED.

Remedy: INSTALLED NEW BRACKET GOT FOUR SCREWS HAD TO PAINT TO MATCH, AND INSTALLED.

Part Return Req: No

Status: Approved

Time Requested: .3

Time Allowed: .3

Sublet Repairs: 0.00