

e-Authorization

11/22/20
01:36:49

Authorization number PA03308959 Reference no: 69340 Status: Approved Approved by flins
 Billing Name Address Address VIN Retail sold on
 Basden's American RV Basden's American RV 4YDTSSGG19N10916 5/11/2022
 600 E Baseline Rd
 Evansville, IN 47725

Job operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4132106B Water Heater - Sl	0.00	0.50	0.50		1	0.50	Complaint:CHECK WATER HEATER NOT WORKING ON GAS RIGHT WILL COME ON 30 SECS AND SHUTS OFF AND ABOUT 5 MINS LATER IS COMES BACK ON.... BUT WHEN ON CITY IT WORKS IT GETS TOO HOT AND STARTS BLOWING OUT THE VALVE Cause:THERMO AND EST FAILED Correction:filled water heater with water and check temp it was 165 degrees,that it to hot,replaced thermostat and ecn, filled with water again and it was 150 and no water was coming out of pop off valve.
2	3400706B Pantry Rack - Lat	0.00	0.20	0.20		1	0.30	Complaint:THE MURPHY BED FALLS IT IS SITTING ON THE COUNTER Cause:MOUNT CAME OUT Correction:HAD TO GET NEW SCREWS TO MOUNT LATCH,REINSTALLED LATCH AND DRILLED NEW HOLE FOR LATCH TO CATCH.
3	1201128A Enclosed Underb	0.00	0.40	0.40		1	0.50	Complaint:FRONT BPASSANGER UNDERLINER THE UNDER BELLY IS BUNCHED UP IN THE FRAME Cause:INSTALLED WRONG Correction:CUT EXCESS UNDERBELLY OFF AND TOOK SCREWS OUT TO REINSTALL UNDERPENING THE RIGHT WAY,REINSTALLED SCREWS AND PUT UNDERBELLY TAPE ON FOR REENFORCEMENT.
4	1216002A Step - Fold Up	0.00	0.10	0.10		1	0.10	Complaint:ONE OF THE STEP LEGS ON THE FOLD OUT STAIRS IS STUCK CHECK AND ADVISE Cause:LEG STUCK Correction:TOOK OUT LEG AND SANDED DOWN,TO MUCH PAINT ON LEG IT WAS BINDING UP,NOW IT WORKS GREAT.
Authorization number PA03308959				1.20				

paper claims only use one pre-authorization number per warranty claim for
 Please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

e-Authorization

1/12/2020
01:36:49

Authorization number PA03308959 Reference no: 69340 Status: Approved Approved by flins
 Billing Name Address Address VIN Retail sold on
 Basden's American RV Basden's American RV 4YDTSSGG19N10916 5/11/2022
 600 E Baseline Rd
 Evansville, IN 47725

Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4132106B Water Heater - Su	0.00	0.50	0.50		1	0.50	Complaint:CHECK WATER HEATER NOT WORKING ON GAS RIGHT WILL COME ON 30 SECS AND SHUTS OFF AND ABOUT 5 MINS LATER IS COMES BACK ON... BUT WHEN ON CITY IT WORKS IT GETS TOO HOT AND STARTS BLOWING OUT THE VALVE Cause:THERMO AND EST FAILED Correction:filled water heater with water and check temp it was 165 degrees,that it to hot,replaced thermostat and ecm,filled with water again and it was 150 and no water was coming out of pop off valve.
2	3400706B Pantry Rack - Lat	0.00	0.20	0.20		1	0.30	Complaint:THE MURPHY BED FALLS IT IS SITTING ON THE COUNTER Cause:MOUNT CAME OUT Correction:HAD TO GET NEW SCREWS TO MOUNT LATCH,REINSTALLED LATCH AND DRILLED NEW HOLE FOR LATCH TO CATCH.
3	1201128A Enclosed Underb	0.00	0.40	0.40		1	0.50	Complaint:FRONT BPASSANGER UNDERLINER THE UNDER BELLY IS BUNCHED UP IN THE FRAME Cause:INSTALLED WRONG Correction:CUT EXCESS UNDERBELLY OFF AND TOOK SCREWS OUT TO REINSTALL UNDERPENING THE RIGHT WAY,REINSTALLED SCREWS AND PUT UNDERBELLY TAPE ON FOR REENFORCEMENT.
4	1216002A Step - Fold Up	0.00	0.10	0.10		1	0.10	Complaint:ONE OF THE STEP LEGS ON THE FOLD OUT STAIRS IS STUCK CHECK AND ADVISE Cause:LEG STUCK Correction:TOOK OUT LEG AND SANDED DOWN,TO MUCH PAINT ON LEG IT WAS BINDING UP,NOW IT WORKS GREAT.
Authorization number PA03308959				1.20				

paper claims only use one pre-authorization number per warranty claim for
 multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the