

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69343
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11015 - 2023 CHEROKEE 274RK 4X4TCKC28PX160894
VIN: 4X4TCKC28PX160894 HIN: SER#: 4X4TCKC28PX160894
Mileage: 0 Work Order Comp: 25 JAN 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 16 NOV 22 Inv #: 387028

WO # Job # Description JOB INFORMATION

69343 3 THE LIGHTS ON THE RANGE WILL NOT TURN OFF.
THE LIGHTS ON THE RANGE WILL NOIT SHUT OFF. install new range.
Lights on range will not turn off completly. Either knob lights
are "ON" or the oven light is "ON". The center position on
switch should be everything "OFF". Also the light on the
sparker knob is nt working. 11/22/2022: Turned in parts request
for a new range. pulled unit in shop. removed range. removed new
range from box. installed new range in unit. hooked up to shore
power. lights shut off as they should. cleaned up mess. parked
unit.
69343 2 THE STEPS HIT THE DOOR FRAME.
THE STEPS HIT THE DOOR FRAME.
The steps hit the door frame when trying to fold out. Removed
mounting screws. Shifted steps over to center in door frame
opening. Replaced mounting screws. Adjusted latch to secure
steps in up position.
69343 4 THE TV ANTENNA DOES NOT PICK UP ANY CHANNELS
THE TV ANTENNA DOES NOT PICK UP ANY CHANNELS.
Removed Booster from ceiling mounting and removed roof TV
Antenna. Checked coax . Coax good. Checked coax from booster to
cable hook-up and found it was good. Checked coax from booster
to front tv and to outside tv was shorted. Removed bathroom
ceiling vent cover and skylight cover to check for pinched coax
cables or a screw thru coax cables. Removed radio from cabinet

Claim : 69343

 WO # Job # Description JOB INFORMATION

 mount. Checked coax cables connector to splitter behind radio. Found all coax cables connected to splitter on the wrong connectors. Removed coax cables from splitter and reconnected to correct inlet and outlets. Checked operation of TV Antenna and test TV for channels. TV now picking up channels. Remounted all cable outlets that were removed. Remounted radio in cabinet. Rechecked all TV outlrlt connections with test TV. All outlets are good.

69343 5 BULB SEAL ABOVE SLIDE OUT COMING OFF
 BULB SEAL ABOVE SLIDE OUT COMING OFF.
 Moved unit back into shop from sales lot. Slide out bulb seal came loose and slid out at rear of slide out. Removed old bulb seal from above slide out. Cleaned off all olf factory sealer that was put on very sloppy. Installed new bulb seal and secured in place with a screw at both ends of seal. Applied clear silicone to seal gap between bulb and side of unit.

 Part No Job# Description PARTS Qty Price Total

 F100354622 3 17" GAS RANGE - FURRIION/GIRARD 1.00 407.43 407.43

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 1.00 150.00 150.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.50 150.00 225.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.63 150.00 94.50
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.37 150.00 55.50
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.50 150.00 225.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.50 150.00 75.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 3 FREIGHT-RANGE 1.00 120.00 120.00

Parts Total: 407.43
 Labour Total: 840.00
 Sublet Total: 0.00
 Extras Total: 120.00

>>>> Claim Total: 1,367.43