



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69343
Promised Date:
24 DEC '22



CUSTOMER WORK ORDER

WO #: 69343

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: PH

Location: 0125 BH TO CLOSE

Stock #: 11015

Stock Desc: 2023 TT FOREST RIVER
CHEROKEE 274RK

Chassis #: 4X4TCKC28PX160894

Serial #: 4X4TCKC28PX160894

Mileage: 0

Licence:

Invoice #:

Date In: 16 NOV 22

Promised: 31 DEC 22

Date Sched:

Completed: 25 JAN 23

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*69468 on 01 DEC 22

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Removed factory battery from battery box. Drilled drain holes in bottom of box. Reinstalled battery. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Checked roof and awning. Checked entrance door and all compartment doors. Operated stab jacks. Checked power cord. Checked converter output. Checked all interior lights. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked all windows and blinds. Checked all cabinets and drawers. Checked all interior doors. Filled fresh water tank. Flushed antifreeze from water lines and faucets. Checked all water lines and faucets for leaks. Filled all holding tanks and checked monitor panel. Checked all appliances. Performed LP drop test and set LP pressure at 11 in.wc. Connected to air pressure and blew out all water lines and faucets. Added antifreeze to all water lines and faucets, including both outside showers. Poured antifreeze in all drain traps. Water heater does not have a by-pass. Drained all holding tanks. Applied all company decals. Checked Radio and Fireplace. Recorded all serial numbers and took pictures. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: WATER HEATER EXHAUST PIPE NOT OUT DOOR

CAUSE: WATER HEATER EXHAUST PIPE NOT OUT DOOR.

CORRECTION: Checked water heater exhaust pipe. Pipe is in alignment when water heater door is closed and in correct position.

Labor

Printed On: 1/25/2023 12:18:26PM

© 2023 Integrated Dealer Systems



Customer #:
1000





Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Subtotal for Job #1:			0.00

Job #2 - Warranty

COMPLAINT: THE STEPS HIT THE DOOR FRAME.

CAUSE: THE STEPS HIT THE DOOR FRAME.

CORRECTION: The steps hit the door frame when trying to fold out. Removed mounting screws. Shifted steps over to center in door frame opening. Replaced mounting screws. Adjusted latch to secure steps in up position.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	15.00
Subtotal for Job #2:			15.00

Job #3 - Warranty

COMPLAINT: THE LIGHTS ON THE RANGE WILL NOT TURN OFF.

CAUSE: THE LIGHTS ON THE RANGE WILL NOIT SHUT OFF.
 install new range.

CORRECTION: Lights on range will not turn off completly. Either knob lights are "ON" or the oven light is "ON". The center position on switch should be everything "OFF". Also the light on the sparker knob is nt working. 11/22/2022: Turned in parts request for a new range.
 pulled unit in shop. removed range. removed new range from box. installed new range in unit. hooked up to shore power. lights shut off as they should. cleaned up mess. parked unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	150.00

Parts

Part #	Description	Qty	Price	Total
F100354622	17" GAS RANGE - FURRION/GIRARD	1.00	407.43	407.43

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-RANGE	1.00	120.00	120.00

Subtotal for Job #3: 677.43

Job #4 - Warranty

COMPLAINT: THE TV ANTENNA DOES NOT PICK UP ANY CHANNELS

CAUSE: THE TV ANTENNA DOES NOT PICK UP ANY CHANNELS.

CORRECTION: Removed Booster from ceiling mounting and removed roof TV Antenna. Checked coax . Coax good. Checked coax from booster to cable hook-up and found it was good. Checked coax from booster to front tv and to outside tv was shorted. Removed bathroom ceiling vent cover and skylight cover to check for pinched coax cables or a screw thru coax cables. Removed radio from cabinet mount. Checked coax cables connector to splitter behind radio. Found all coax cables connected to splitter on the wrong connectors. Removed coax cables from splitter and reconnected to correct inlet and outlets. Checked operation of TV Antenna and test TV for channels. TV now picking up channels. Remounted all cable outlets that were removed. Remounted radio in cabinet. Rechecked all TV outlrlt connections with test TV. All outlets are good.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



W/O: 69343
Promised Date:
31 DEC 22



Customer #:
1000



Z990	MISC LABOUR CODE (EXTERNAL)	DKM	225.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	94.50
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	225.00

Subtotal for Job #4: 600.00

Job #5 - Warranty

COMPLAINT: BULB SEAL ABOVE SLIDE OUT COMING OFF

CAUSE: BULB SEAL ABOVE SLIDE OUT COMING OFF.

CORRECTION: Moved unit back into shop from sales lot. Slide out bulb seal came loose and slid out at rear of slide out. Removed old bulb seal from above slide out. Cleaned off all old factory sealer that was put on very sloppy. Installed new bulb seal and secured in place with a screw at both ends of seal. Applied clear silicone to seal gap between bulb and side of unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	75.00

Subtotal for Job #5: 75.00

Parts Total: 407.43
Labour Total: 840.00
Sublet Total: 0.00
Extras Total: 120.00
WORK ORDER TOTAL: 1,367.43

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 Jan 2023

