

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1324743
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKC24NX158511
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT274WK
TIMOTHY S BRETZ		DEALER RO #	69347
3252 N CR 275 E		CLAIM START DATE	11/17/2022
Grandview, IN 47615		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	07/30/2022	WARRANTY EXPIRATION DATE	07/30/2023

Claim Line Details

Labor

Line# 1	Operation Code 40-197-01-11-001419	Operational Description 110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/ Replace/Electrical
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-11-17 14:20:32 :: SOME OUTLETS DONT WORK THE GFCI OUTLETS DO NOT WORK THE GFCI OUTLET ON THE CELING WAS BAD. INSTALLED NEW ONE AND TESTED AND WORKED JUST FINE. PUT OLD ONE ON WARANTY SHELF THE GFCI OUTLET ON THE CELING WAS BAD. INSTALLED NEW ONE AND TESTED AND WORKED JUST FINE. PUT OLD ONE ON WARANTY SHELF		
	Model #	Dlr Sub Hrs 0.30
	Serial #	Appr Hrs 0.30
		Sub Labor Amt \$45.00
		Appr Labor Amt \$45.00

Notes

Labor

Line# 2	Operation Code 60-139-01-00-001542	Operational Description Single Handle Kitchen Faucet - Plumbing/Kitchen (Galley) Sink/Replace/ No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-11-17 14:24:16 :: KITCHEN FAUCET LEAKS AT THE BASE LEAKING AT THE BASE NEED TO INSTALL NEW NEED TO INSTALL NEW FAUCET		
	Model #	Dlr Sub Hrs 0.50
	Serial #	Appr Hrs 0.50
		Sub Labor Amt \$75.00
		Appr Labor Amt \$75.00

Notes

Please attach picture of the white tag on the faucet hose lying flat before sending to processing

Labor

Line# 3	Operation Code 30-103-01-00-001129	Operational Description Floor Register - Interior/Flooring/Replace/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-11-17 14:25:13 :: FLOOR AT THE ISLAND IS SQUEEKY WHEN WALKING BY IT floor at island at register vent was squeaking. put some insulation on the vent and stopped squeaking floor at island at register vent was squeaking. put some insulation on the vent and stopped squeaking		
	Model #	Dlr Sub Hrs 0.20
	Serial #	Appr Hrs 0.10
		Sub Labor Amt \$30.00
		Appr Labor Amt \$15.00

Notes

Labor
Line# 4

Operation Code
40-196-01-11-001301

Operational Description
LED Light Strip or Rope Lights - Electrical/12 Volt Interior/Replace/
Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-11-17 14:26:04 :: BOTH ROOM !!!!!BLUE ACCENT
LIGHTS ON BOTH SLIDES ARE HANGING DOWN FOUND LIGHTS ARE FALLING DOWN THE STICKY IS
MISSING NEED TO REPLACE THE LIGHTS ABOVE THE SLIDE ROOMS

Model #	Dlr Sub Hrs	1.00	Sub Labor Amt	\$150.00
Serial #	Appr Hrs	0.40	Appr Labor Amt	\$60.00

Notes

Submitted	Labor Amt	\$300.00
	Parts & Freight	\$0.00
	Total	\$300.00

Approved	Labor Amt	\$195.00
	Parts & Freight	\$0.00
	Total	\$195.00

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.