

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 1336594 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 4X4TCKC27NX155487 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 017 / 017A ITEM # ACKT274BRB DEALER RO # 69348 CLAIM START DATE 11/29/2022 CLAIM END DATE 01/01/1900
Labor rate: \$150.00 OWNER INFORMATION JON A FEHRENBACHER 15600 TRAPP RD Evansville, IN 47720 USA	Retail Date of Purchase 03/29/2022 WARRANTY EXPIRATION DATE 03/29/2023

Claim Line Details

Labor				
Line# 1	Operation Code	Operational Description		
	60-143-01-00-001620	Exterior Shower Faucet - Plumbing/Exterior Shower/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2022-11-29 15:46:15 :: OUT SIDE KITCHEN FAUCETS THEY WONT SHUT OFF. REMOVED OLD FAUCET AND INSTALLED NEW OUTSIDE SHOWER FAUCET			
	Model #	Dlr Sub Hrs	Sub Labor Amt	\$75.00
	Serial #	Appr Hrs	Appr Labor Amt	\$75.00
	Notes			
	thank you			
Labor				
Line# 2	Operation Code	Operational Description		
	20-66-02-00-000678	Screen Door - Exterior/Entry Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2022-11-29 15:46:57 :: FRONT DOOR IS GIVING ISSUES THE SCREEN DOOR IS HANGING DOWN AND YOU HAVE TO PUSH ON IT TO GET IT TO LOCK ADJUSTED HINGES AND DOOR LATCH. IT OPENS AND CLOSES GOOD NOW			
	Model #	Dlr Sub Hrs	Sub Labor Amt	\$15.00
	Serial #	Appr Hrs	Appr Labor Amt	\$15.00
	Notes			
Labor				
Line# 3	Operation Code	Operational Description		
	20-69-02-00-000705	Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2022-11-29 15:49:02 :: THE OUTSIDE KITCHEN DOOR IS WARPED. ADJUSTED HING ON DOOR. ITS FLUSH ON BOTH SIDES			
	Model #	Dlr Sub Hrs	Sub Labor Amt	\$60.00
	Serial #	Appr Hrs	Appr Labor Amt	\$60.00
	Notes			
	thank you			
Labor				
Line# 4	Operation Code	Operational Description		
	RC-026-01-00-004186	22V243, 2022-181 - FLEXTECH QUICK DISCONNECTS - REMEDY		

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-11-29 15:50:06 :: RECALL 22V243 LP QUICK CONNECT REPLACED LP QUICK CONNECT VALVE

Model #	Dir Sub Hrs	0.30	Sub Labor Amt	\$45.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00

Notes

Submitted	Labor Amt	\$195.00	Approved	Labor Amt	\$195.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$195.00		Total	\$195.00

DEALER _____ **DATE** _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE

All repairs described have been inspected and are satisfactory.