

Pre-Authorization

2/7/20
02:20:56 P

Pre-Authorization number PA03364100 Reference no: 69365 Status: Approved Approved by papca Approved date 2/7/2023
 Working Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDFCGL27PV501663 11/17/2022
 600 E Baseline Rd
 Evansville, IN 47725

| Item | Root Description | Sublet | Sub hours | Approved hours | Actual hours | Qty | Base hours | Complaint / Cause / Correction |
|------|------------------------------|--------|-----------|----------------|--------------|-----|------------|---|
| 1 | 3200118A Door - Interior Hin | 0.00 | 0.20 | 0.20 | | 1 | 0.20 | Complaint: PASSENGER SIDE LP DOOR WONT SHUT Cause: HAD TO ADJUST DOOR Correction: ADJUSTED DOOR UP HAD TO TAKE OUT PLASTIC STOPS AND READJUST DOOR TO SHUT RIGHT, ADDED BACK IN THE STOPS. KRV - REPAIR ONLY approved. |
| 2 | 4149014A Refrigerator - 12 \ | 0.00 | 0.20 | 0.20 | | 1 | 0.50 | Complaint: TOP FREEZER DOOR WONT LATCH Cause: ADJUSTED LATCH. Correction: ADJUST FREEZER LATCH KRV - REPAIR ONLY approved. |
| 3 | 4149014A Refrigerator - 12 \ | 0.00 | 0.20 | 0.20 | | 1 | 0.50 | Complaint: BOTTOM OF THE FRIDGE LATCH IS BROKEN Cause: REPLACED BOTTOM LATCH AND ADJUSTED FOR TOP LATCH. BOTH LATCH NOW. Correction: REPLACED BOTTOM LATCH AND ADJUSTED FOR TOP LATCH. BOTH LATCH NOW. KRV - Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item. |

Pre-Authorization number PA03364100
 0.60

For paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the