

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1334693
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKE20NX156381
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT29TE
MICHAEL FRANCIES JR		DEALER RO #	69419
14082 N OLD MADISONVILLE RD		CLAIM START DATE	11/28/2022
Crofton, KY 42217		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	04/30/2022	WARRANTY EXPIRATION DATE	04/30/2023

Claim Line Details

Labor

Line# 1	Operation Code RC-026-01-00-004186	Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-11-28 15:05:22 :: RECALL 22V243 LP QUICK CONNECT replace quick connect per recall removed quick connect. replaced with new one.	
	Model # Serial #	Dlr Sub Hrs 0.30 Appr Hrs 0.30
		Sub Labor Amt \$45.00 Appr Labor Amt \$45.00
	Notes	

Labor

Line# 2	Operation Code 30-102-01-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-11-28 15:06:03 :: TRIM COMING DOWN AT THE KITCHEN AREA ABOVE THE DINNETEE trim was loose pushed trim back into track	
	Model # Serial #	Dlr Sub Hrs 0.20 Appr Hrs 0.20
		Sub Labor Amt \$30.00 Appr Labor Amt \$30.00
	Notes	

Labor

Line# 3	Operation Code 60-141-19-00-001596	Operational Description Tub Surround - Plumbing/Shower, Tub Surround/Reseal/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-11-28 15:06:50 :: AROUND THE BOTTOM OF THE SHOWER WATER IS LEAKING WHILE USING THE SHOWER no silicone on outside of shower surround. applied silicone to outside of surround and inside corners.	
	Model # Serial #	Dlr Sub Hrs 0.30 Appr Hrs 0.30
		Sub Labor Amt \$45.00 Appr Labor Amt \$45.00
	Notes	

Labor

Line# 4	Operation Code	Operational Description
---------	----------------	-------------------------

70-167-19-00-001999

Water Heater - Appliances/Water Heater (Suburban)/Reseal/No Tread
Code**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2022-11-28 15:16:18 :: THE SCREWS COME OUT FROM THE BOTTOM SIDE OF THE WATER HEATER DOOR WHEN DRIVING DOWN THE ROAD. screws are backing out on the bottom. removed screws and replaced with larger screws.

Model #**Dir Sub Hrs**

0.10

Sub Labor Amt \$15.00**Serial #****Appr Hrs**

0.10

Appr Labor Amt \$15.00**Notes****Submitted**

Labor Amt	\$135.00
Parts & Freight	\$0.00
Total	\$135.00

Approved

Labor Amt	\$135.00
Parts & Freight	\$0.00
Total	\$135.00

DEALER**DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER**DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.