



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69421
Promised Date:
22 NOV 22



CUSTOMER WORK ORDER

WO #: 69421

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:
Author: PH
Location: BACKUP

Stock #: 11172
Stock Desc: 2023 TT COACHMEN
FREEDOM EXPRESS 274RKS
Chassis #: 5ZT2FESB1PW026826
Serial #: 5ZT2FESB1PW026826
Mileage:
Licence:

Invoice #:
Date In: 25 NOV 22
Promised: 30 NOV 22
Date Sched:
Completed: 30 NOV 22
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*69478 on 02 DEC 22
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: PDI NEW UNIT

CORRECTION: PDI NEW UNIT

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*69478 on 02 DEC 22
Estimate amount was 0.00
WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

CAUSE: winterized unit took 2 gals

CORRECTION: winterized unit took 2 gals

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Customer #:
1000



W/O: 69421
Promised Date:
30 NOV 22



Customer #:
1000



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: TV CABINET LATCH BROKE CAUSING TV CABINET TO OPEN

CAUSE: tv cabinet latch was broke off re intalled with new screw

CORRECTION: tv cabinet latch was broke off re intalled with new screw

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	30.00

Subtotal for Job #1: 30.00

Job #2 - Warranty

COMPLAINT: BATHROOM DOOR NOT LATCHING RIGHT

CAUSE: bathroom door was not latching properly adjusted strike plate

CORRECTION: bathroom door was not latching properly adjusted strike plate

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	30.00

Subtotal for Job #2: 30.00

Job #3 - Warranty

COMPLAINT: SHOWER SURROUND NOT SEALED

CAUSE: shower surround was not sealed up at top

CORRECTION: sealed up shower surround

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	45.00

Subtotal for Job #3: 45.00

Parts Total: 0.00
Labour Total: 105.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 105.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Dec 2022

