

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69435
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11009 - 2023 CHEROKEE 264DBH 4X4TCKB28PX160993
VIN: 4X4TCKB28PX160993 HIN: SER#: 4X4TCKB28PX160993
Mileage: 0 Work Order Comp: 20 DEC 22
Auth. No: Dealer #:
Warr. Date: Work Order Date: 28 NOV 22 Inv #: 386310

WO # Job # Description JOB INFORMATION

69435 1 FURANCE MAKING A NOISE WHEN RUNNING
FURANCE MAKING A SOUND. PULLED THE INTAKE OFF UNHOOKED THE GAS
LINE AND BENCH TESTED IT AND FURANCE IS NOT MAKING A NOISE. PUT
THE FURANCE BACK IN AND FOUND THE FAN MAKING NOISE AND HITTING
THE CAGE THE GASKET ON THE FLOOR WAS TORE UP AND NEEDS REPLACED
ALSO
recieve new blower fan then installed on furnace and bench
tested. placed furnace inside camper and tested furnace again.
69435 8 ACCENT LIGHT FOR OUTSIDE IS BROKEN (WOLF HOLOGRAM LIGHT)
ACCENT LIGHT WAS BROKEN REPLACED AND TESTED
ACCENT LIGHT WAS BROKEN REPLACED AND TESTED
69435 2 WATER HEATER DOOR HAS SILICONE ALL OVER IT
door was sealed on the hinge side from factory with geocell.
removed door from flange. pulled off larger chunks from door. got
a small pan and filled with mineral spirits to soften up sealer.
removed from mineral spirits and cleaned the rest off with a
towel. cleaned up excess from water heater flange. installed
door.
69435 3 BEDROOM DOOR IS HITTING DOOR FRAME
DOOR IS RUBBING ON DOOR LATCH.
REMOVED DOOR LATCH AND PLASTIC DOOR FRAME. TOOK A CHISEL AND CUT
AWAY WOOD TO MAKE LATCH PULL INTO THE FRAME. INSTALLED FRAME AND
LATCH. CLEANED UP MESS.

Claim : 69435

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
69435      4      BLACK MARKS ON SLIDE OUT CEILING
                MARK ON CIELING NEXT TO LIGHT.
                REMOVED WITH MINERAL SPIRITS AND A TOWEL

69435      5      BLACK SILICONE ON DOOR THRESHOLD
                SILICONE NEEDS REMOVED
                REMOVED WITH MINERAL SPIRITS AND A TOWEL

69435      11     SUBWOOFER FOR RADIO ISNT WORKING
                puuled radio to check connections. all connections are good.
                removed subwoofer from ceiling. wire terminal came loose.
                crimped terminal with pliers and secured to speaker. installed
                subwoofer to ceiling.

69435      12     FRONT SCREEN DOOR LATCH NEEDS TO BE ADJUSTED.
                latch isnt holding door.
                loosened screws and pulled down latch so it will hold onto screen
                door.

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
69-7047      1      350206 SUBURBAN BLOWER WHEEL      1.00      14.74      14.74
7586         1      SUBURBAN A/C FURNACE GASKET      1.00      3.23      3.23
F100327988   8      LIGHT, DRGLO WOLF HEAD EXTERIOR L  1.00      26.21      26.21

```

```

*****
Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total
*****
Z990          1      MISC LABOUR CODE (EXTERNAL)      0.90      150.00      135.00
Z990          8      MISC LABOUR CODE (EXTERNAL)      0.79      150.00      118.50
Z990          8      MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00
Z990          2      MISC LABOUR CODE (EXTERNAL)      0.10      150.00      15.00
Z990          2      MISC LABOUR CODE (EXTERNAL)      0.00      150.00      0.00
Z990          3      MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00
Z990          4      MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00
Z990          5      MISC LABOUR CODE (EXTERNAL)      0.30      150.00      45.00
Z990          11     MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00
Z990          12     MISC LABOUR CODE (EXTERNAL)      0.10      150.00      15.00

```

```

*****
Excode      Job#      Description      EXTRAS      Qty      Price      Total
*****
FRT          8      UPS-LIGHT      1.00      15.89      15.89

```

```

Parts Total:      44.18
Labour Total:      448.50
Sublet Total:      0.00
Extras Total:      15.89

```

>>>> Claim Total: 508.57