

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69443
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 10894 - 2023 CHEROKEE WOLF PUP 25JB 5ZT2CKPB8PY028366
VIN: 5ZT2CKPB8PY028366 HIN: SER#: 5ZT2CKPB8PY028366
Mileage: 0 Work Order Comp: 15 DEC 22
Auth. No: Dealer #:
Warr. Date: Work Order Date: 29 NOV 22 Inv #: 386202

WO # Job # Description JOB INFORMATION

69443 5 LP TANK STRAP LATCH IS BROKEN
LP TANK STRAP LATCH IS BROKEN.
Checked loose strap on lp tank. Latch is broken on strap.
Turned in parts reques for a new strap.

69443 6 CEILING LIGHT OVER DINETTE WON'T WORK
LIGHT OVER DINETTE TABLE DOES NOT WORK.
Checked operation of ceiling light over dinette table. Dors not
come on with switch. Removed from ceiling. Wiring to light have
power and are connected correctly. Disconnected light from power
wires. Connected directly to battery still does not work no
matter which position switch is in. Turned-in parts request for
a new ceiling light. 12/8/2022: Received new ceiling light.
Installed new ceiling light over dinette. Checked operation of
new light. OK. Moved unit back to sales lot.

69443 9 THE BLACK TANK FLUSHER HOSE IS PINCHED FLAT
THE BLACK TANK FLUSHER HOSE IS PINCHED FLAT.
The FACTORY ran the black tank flusher hose between the frame and
floor smashing it flat tight. Can not pull hose out. Cut hose
off on both sides of frame. Cut piece of new hose to fit and
spliced together around frame.

69443 1 FRONT CAP IS DENTED DRIVERS SIDE
FRONT CAP IS DENTED ON DRIVERS SIDE.
Front sheet metal is wavey next to corner trim at top of roadside

Claim : 69443

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
          edge. Taped off area and filled void at trim with clear
          silicone.

69443      3      SLIDE OUT FACIA "TOP" HAS STAPLES POKING OUT
          SLIDE OUT FACIA "TOP" HAS STAPLES POKING OUT.
          Removed brad nail that was sticking out of facia trim. Filled
          hole with matching putty.

69443      7      RADIO NOT WORKING...ONLY STATIC
          RADIO NOT WORKING--ONLY STATIC.
          Removed radio from cabinet. Checked all speaker connections.
          All good. Checked antenna connection. Connector on cable was
          loose. Cut off connector and installed new coax connector.
          Radio now playing without static. Remounted radio back in
          cabinet.

69443      8      PANTRY DOOR WON'T LATCH CLOSED...NOTED AT TIME OF DELIVERY.
          PANTRY DOOR WON'T LATCH CLOSED ....NOTED AT TIME OF DELIVERY.
          Latch plate mounted too low and too far back. Removed latch
          plate. Trimmed plastic door frame and enlarged plunger hole.
          Remounted latch plate to align with door knob plunger. Door now
          latches closed.

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
F100060395    5   STRAP, LP TANK/SPARE TIRE HOLD DO  1.00      4.93      4.93
40E15514A     6   LIGHT, 4 1/2" LED PUCK LIGHT WITH  1.00      2.43      2.43
51132         9   1/2" BRASS PEX COUPLING             2.00      1.53      3.06
F100041177    9   1/2" BLUE PVC HIGH PRESSURE HOSE    2.00      0.24      0.48

```

```

*****
Lab Code Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      5   MISC LABOUR CODE (EXTERNAL)          0.15     150.00     22.50
Z990      5   MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00
Z990      5   MISC LABOUR CODE (EXTERNAL)          0.15     150.00     22.50
Z990      6   MISC LABOUR CODE (EXTERNAL)          0.12     150.00     18.00
Z990      6   MISC LABOUR CODE (EXTERNAL)          0.00     150.00      0.00
Z990      6   MISC LABOUR CODE (EXTERNAL)          0.08     150.00     12.00
Z990      9   MISC LABOUR CODE (EXTERNAL)          0.30     150.00     45.00
Z990      1   MISC LABOUR CODE (EXTERNAL)          0.50     150.00     75.00
Z990      3   MISC LABOUR CODE (EXTERNAL)          0.10     150.00     15.00
Z990      7   MISC LABOUR CODE (EXTERNAL)          0.10     150.00     15.00
Z990      8   MISC LABOUR CODE (EXTERNAL)          0.20     150.00     30.00

```

```

*****
Excode Job#   Description      EXTRAS      Qty      Price      Total
*****
FRT      6   UPS-LIGHT          1.00     15.95     15.95

```

Claim : 69443

 Excode Job# Description EXTRAS Qty Price Total

Parts Total: 10.90
 Labour Total: 255.00
 Sublet Total: 0.00
 Extras Total: 15.95
 >>>> Claim Total: 281.85

Customer Signature: _____

Date: _____