

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1341473
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKE21PX161012
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT29TE
		DEALER RO #	69444
		CLAIM START DATE	12/02/2022
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 10-7-02-00-000141	Operational Description Entry Step - Frame & Chassis/Manual Entry Step/Adjust/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-12-02 13:19:11 :: ENTRY STEPS HITTING DOOR FRAME ENTRY STEPS HITTING DOOR DUE TO LATCH ON STEP TO FAR FORWARD CASUING IT TO HIT HINGE ADJUSTED LATCH			
	Model #	Dlr Sub Hrs	0.20	Sub Labor Amt \$30.00
	Serial #	Appr Hrs	0.10	Appr Labor Amt \$15.00

Notes

Labor

Line# 2	Operation Code 30-102-12-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-12-02 13:20:10 :: BATTEN STRIPS LOOSE NEXT TO PANTRY AND IN HALLWAY BATTEN STRIP NEAR PANTRY WAS LOSE AND NEEDED STAPLED BATTEN STRIP NEAR PANTRY WAS LOSE AND NEEDED STAPLED			
	Model #	Dlr Sub Hrs	0.20	Sub Labor Amt \$30.00
	Serial #	Appr Hrs	0.10	Appr Labor Amt \$15.00

Notes

Labor

Line# 3	Operation Code 30-101-02-00-001076	Operational Description Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-12-02 13:20:56 :: REAR BEDROOM DOOR IS HITTING FRAME REAR BEDROOM DOOR WAS HITTING GRAM DUE TOE STRIKING PLATE AND FRAME NEEDING ADJUSTED REAR BEDROOM DOOR WAS HITTING GRAM DUE TOE STRIKING PLATE AND FRAME NEEDING ADJUSTED. ADJUSTED STRIKING PLATE AND FRAME			
	Model #	Dlr Sub Hrs	0.20	Sub Labor Amt \$30.00
	Serial #	Appr Hrs	0.20	Appr Labor Amt \$30.00

Notes

Labor

Line# 4	Operation Code 30-100-02-00-003062	Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread		
---------	---------------------------------------	---	--	--

Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-12-02 13:21:35 :: DOORS ABOVE SINK ARE RUBBING
DOORS ABOVE SINK WERE RUBBING HINGES AND LATCHES NEED TO BE MOVED OVER SOME MOVED
HINGES AND LATCHES SLIGHTLY TO KEEP DOORS FROM RUBBING

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$30.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$30.00

Notes

auth as requested

Labor

Line# 5

Operation Code

70-469-02-00-004029

Operational Description

Door Latch or Catch - Appliances/Refrigerator (Furrion)/Adjust/No Tread
Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-12-02 13:22:29 :: SEALANT ON FRIDGE DOOR
SEALANT ON FRIDGE DOOR REMOVED SELANT FROM FRIDGE DOOR

Model #	NA	Dlr Sub Hrs	0.20	Sub Labor Amt	\$30.00
Serial #	NA	Appr Hrs	0.10	Appr Labor Amt	\$15.00

Notes

Submitted

Labor Amt	\$150.00
Parts & Freight	\$0.00
Total	\$150.00

Approved

Labor Amt	\$105.00
Parts & Freight	\$0.00
Total	\$105.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.